


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350℃, 50 Watt max . and use a pencil tip.
- 4. Put tip to wire in solder cup.
- 5. After 1 second bring in solder.
- 6. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 7. Remove soldering iron.
- 8. Wait until solder gets rigid again.
- 9. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



Γ	T HQH	HAND					tolerance		T_{-}	\overline{A}	scale: 3:1
	A HOU	DO NOT ALTER CAD DRAWING BY HA								Ψ	material: SEE SHEET 1
	AY NOT BE COPIED OR INY WAY, AND MAY NOT A THIRD PARTY WITHOUT JION. COPYRIGHT OF CONEC GMBH								dim.	dim. in mm	
								date	nam		title:
							drawn	09.07.13	Lehmen	kühler	RECOMMENDED PANEL CUT-OUT
	NOT BE ' WAY, A THIRD F 'N.						appd.	11.07.13	Fiscl	ner	D-SUB FEMALE 25pos. SOLDER CUP
	NO TANK						norm				with threaded lock and 4-40 UNC stud bolt
	ING MAY PED IN ANY ON TO A TERMISSION PAUD COF						d-old				dwg no: DIN-
	MIN SED						CON				A51/4 A 4 0 0 0
	THIS DRAWING MAY NC REPRODUCED IN ANY W BE PASSED ON TO A TH WRITTEN PERMISSION.		а	Original					N E	₽®	15K1A1338
			rev.	description	date	name	•		48		part no: SEE SHEET 1
	l		D		$\overline{\Lambda}$		C				В А