

TABLE OF CONTENTS

A. SAFETY INSTRUCTIONS

- 1. Safety Information
- 2. International Symbols

B. PRODUCT DESCRIPTION

C. SPECIFICATION

- 1. Basic Specification
- 2. Features
- 3. Digital Multimeter Specification
- 4. General Specification

D. PARTS AND NAMES

- 1. Display
- 2. Rotary Switch
- 3. Push Buttons

E. MEASUREMENT TECHNIQUES

- 1. Measuring DC/AC Volts
- 2. Measuring DC/AC Amps
- 3. Measuring Resistance and Continuity Test
- 4. Measuring Diodes
- 5. Measuring Capacitance and Coil
- 6. Measuring Frequency and Temperature
- 7. Using Adapters

F. ADDITIONAL FUNCTIONS

- 1. Data Logging
- 2. Memory/Recall
- 3. Relative
- 4. Compare
- 5. Record
- 6. Data Hold
- 7. Auto/Manual Range
- 8. RS-232 Interface

G. SET UP MODE

H. MAINTENANCE

- 1. Cleaning
- 2. Fuse Replacement
- 3. Battery Replacement

A. SAFETY INSTRUCTIONS

This manual contains safety messages and warnings that must be obeyed to use the instrument safely and properly. Please follow the manufacturer's procedures through out this manual. Improper use may lead to damage the safety protection provision.

1. Safety Information

• TPI192Ⅲ

a) Over Voltage 1000Vdc / 750Vac (Category II) b) Over Voltage 600V (Category III)

• TPI194II

a) Over Voltage 1000V (Category III) b) Over Voltage 600V (Category IV)

2. International Symbols

- a) \sim Alternating Current (AC)
- b) == Direct Current (DC)
- c) 🛆 WARNING!
- d) 🛆 CAUTION !: RISK OF ELECTRIC SHOCK
- e) 🛓 GROUND
- f) DOUBLE INSULATION
- g) 🖶 FUSE

B. PRODUCT DESCRIPTION

- a) Main Body
- b) Test Lead
- c) Protection Boot
- d) RS-232 Cable and CD
- e) Accessory
- · K type thermocouple probe
- Current Adapter A254 (10/60A)
- Current Adapter A256 (40/400A)
- Current Adapter A296 (400/1000A)

C. SPECIFICATION

- 1. Basic Specification a) DC Voltage:0~1000V
- b) AC Voltage: 15mV~1000V
 c) Accuracy
 DC Voltage: ± (0.05% + 5)
 AC Voltage: ± (0.4% + 40)
- d) DC Current: 0-10A
- e) AC Current : 20 µA ~10A

- f) Resistance : 0Ω~50MΩ
- g) Capacitance: 0.01nF~20mF
- h) Coil: 0.01mH~300mH
- i) Temperature : -50 °C 1350 °C (-54 °F 2462 °F)
- j) Frequency : 0.5Hz~5MHz

2. Features

- a) Triple Display: 50000 count
- b) Analog Bar Graph : 51 segments
- c) Back Light : Allows viewing the display in dark.
- d) MIN/MAX Mode: Displays Minimum and Maximum Average Values
- e) Compare : Compares the measured value to reference value and displays the result as HI, LO, or PASS
- f) Hold : Holds the readings on LCD (Two readings will be held automatically)
- g) Record with Time Stamp: Stores the measured values in preset time intervals with its measured time.
- h) Storage and Reading
- i) Transfer the measured Values to Computers (RS-232C)
- 3. Digital Multimeter Specification

a) DC millivoltage

	Range	Resolution	Accuracy
	50mV	1μV	0.05%+5
Ì	500m	10µV	0.0376+3

b) DC Voltage

Range	Resolution	Accuracy
5V	100µV	0.05%+5
50V	1mV	0.0570+5
500V	10mV	0.1%+5
1000V	100mV	0.1%+5
N. CENCLEMENT INC.		

c) AC Voltage

		Accuracy		
Range	Resolution	50Hz ~ <450Hz	450Hz~ <5KHz	
5V	100µV		0.6%+40	
50V	1mV	0.4%+40		
500V	10mV			
1000V	100mV			

* Frequency sensitivity : more then 20% of F/S

Dongo	Resolution	Accuracy	
Range	ange nesolution	5KHz~ <20KHz	20KHz~ 50KHz
5V	100 µV	0.8%+40	0.8%+60
50V	1mV		
500V	10mV		
1000V	100mV		1

d) Resistance

Range	Resolution	Accuracy
50Ω	1mΩ	1% +10
500Ω	10m Ω	
5ΚΩ	100mΩ	0.05%+10
50KΩ	1Ω	
500KΩ	10Ω	33
5MΩ	100Ω	1%+10
50MΩ	1ΚΩ	170+10

e) DC Current

Range	Resolution	Accuracy
500µA	0.01µA	
5000 µА	0.1µA	0 1504 10
50mA	1μA	0,15%+10
500mA	10μΑ	
5A	100µA	0.007 5
10A	1mA	0.3%+5

f) AC Current

5

Range	Resolution	Accuracy
500µA	0.01µA	
5000 µА	0.1µA	0.75%+10
50mA	1µА	
500mA	10μΑ	. 5
5A	100µA	1.5%+5
10A	1mA	

g) Capacitance

Range	Resolution	Accuracy
5nF	0.01nF	
50nF	0.1nF	
500nF	1nF	2%+10
5μF	10nF	
50µF	100nF	
500mF	1μF	
5mF	10µF	
20mF	100µF	

h) Inductance

Range	Resolution	Accuracy
50mH	0.01mH	5%+80
300mH	0.1mH	5%+50

i) Temperature

Range	Resolution	Accuracy
-50°C ~ 1350°C	0.1°C	2%+/-1℃
- 54°F ~ 2462°F	0.1° F	3%+/-1°F

j) Diode

Range	Test Current	Drop Out Voltage
5V	1mA	3V

k) Continuity Test

500Ω < 1mS 3V	Range	Response Time	Drop Out Voltage
	500Ω	<1mS	3V

• Standard Level : Beeps under 10Ω and stops over 60Ω

I) Frequency

Range	Resolution	Accuracy	
50Hz	0.001Hz		
500Hz	0.01Hz		0.0200
5KHz	0.1Hz		0.000
50KHz	1Hz	0.05%+5	1000
500KHz	10Hz	10-112-122-12-14-14-14-14-14-14-14-14-14-14-14-14-14-	1000
5MHz	100Hz		

6

* Minimum Frequency : 0.5Hz * Sensitivity : 0.5Hz ~ 5Hz : 600mV 5Hz ~ 500kHz : 250mV 500KHz ~ 5MHz : 400mV

m) Duty Cycle

D. PARTS AND NAMES



2. Rotary Switch



OFF	Turns the instrument off. When not use the instrument, set the rotary switch at OFF
¦器)	Measures 0-1000V AC. Press button to change the functions in orders of ACV \rightarrow dB \rightarrow Hz \rightarrow ACV.
ac dc V	Measures 0-1000V DC. Press \bigcirc button to Change the functions in order of DCV \rightarrow ac+dc \rightarrow DCV
Adp	Uses to select the Adapters. Press button to change AC to DC and press RANGE button to select the Adapter.
mV	Measures 0-500mV. Due to the high input impedance in this range, the 0.000mV would not be displayed when the input is open. Should not be a problem when measuring an actual value. Press when to select AC or DC.
nS∜ Ω	Measures 0-50M Ω . Press \bigcirc button to select the function in orders of $\Omega \rightarrow nS \rightarrow Beep$.
₩	Measures forward voltage drop of the diode
*	Measures o.o1nF-20mF capacitor or 0.01mH- 300mH coil. Press button to select coil or capacitor.
ЪС F Hz	Measures frequency or temperatures using K- type thermocouple. Pressbutton to select the function in orders of $Hz \rightarrow C \rightarrow F$.
≝∰ ⊭And	Measures 0-5000uA DC or AC current. Press button to change the function in orders of DCuA \rightarrow AcuA \rightarrow ac + dc uA.
mÃoc	Measures 0 - 500mA DC or AC current. Press button to change the function in orders of DcmA \rightarrow AC mA \rightarrow ac + dc mA.
≊a¢ Ado	Measures 0-10A DC or AC current. Press button to change the function in orders of DCA \rightarrow ACA \rightarrow ac + dc A.

8

3. Push But	tone
5. Fusit Dut	1me peak LOGGING LOAD
	RANGE RECH RELXA EDIT
RANGE	To select the measuring ranges.
REC>	To get MIN, MAX, AVG of the measured values
RELSA	To get relative value as a % of reference value
EDIT	Use with est and ever buttons. To set up the
(10/00) PLC	reference, high, low value.
*	To turn on the backlight
COMP 4	To compare the actual reading to LOW and HIGH values.
HOLDY	To hold and display the measured value on the display.
\bigcirc	To change the functions or features on rotary switch. (Both black and orange colored prints)
LOGGING	A mode to store the measured value and its measured time periodically.
LOAD	To re-display the stored values in LOGGING
MEM	To store the measured value by user during the
	measurement
RCL	To recall and display the stored value in MEM.
CLR	To erase (clear) the all stored values in MEM.

E. MEASUREMENT TECHNIQUE

1. Measuring AC/DC voltage

Do not attempt to make a voltage WARNING! measurement of more than 1000V AC (194II) or 750V AC (192II) and 1000V DC or of a voltage level that is unknown.

Measuring Range

9

mV: 50mV, 500mV(DC), 500mV (AC) ACV/DCV: 5V, 50V, 500V, 1000V

Test Lead and Rotary Switch set-up

Rotary Switch	Black Test Lead	Red Test Lead
ac V	СОМ	VΩ-¥Hz
Hz V		
m V		

- a) To measure the voltage, set up the rotary switch and the test lead as shown above.
 - b) Connect the test leads to the circuit to be measured
 - c) To measure frequency or dBm(dbV) in AC volt, press D button. (function will be changed in orders of ACV -> dB -> frequency)
 - d) In measuring DC voltage, Both AC and DC in a signal that contains ac and dc can be measured at the same time. Press \bigcirc button in orders of DC V \rightarrow ac + dc
 - e) In measuring mV, press C to change ac to dc.
 - dBm = 10 x log (display value / stored value) Reference value can be re-set by user in SETUP mode, and preset value is 600Ω
 - dBV = 20 x log (display value / stored value) Reference value can be re-set by user in SETUP mode, and preset value is 1V
 - ac + dc function



To measure the source shown above, 4.4721 will be displayed in main LCD for AC + DC, 2.0000 in lower left hand side sub-display for AC value, and 4.0000 in lower right hand side sub-display for DC value.

2. Measuring AC/DC Current

WARNING!	Do not attempt to make a current
	measurement of circuits with more than
	1000V (194II) or 600V (192II) present.

CAUTION Do not attempt to make a current measurement with the test lead connected in parallel with the circuit or parts to be tested. Set up the right positions of rotary switch and test leads.

10

Measuring Range uA: 500µA, 5000µA

mA: 50mA. 500mA A:5A.10A

Test Lead and Rotary Switch set-up

Rotary Switch	Black Test Lead	Red Test Lead
aee A de	СОМ	µmA-Φ-TEMP
mA dc		
ac Ado		A

a) Disconnect the power to the circuit to be measured.

b) To measure the current, set the rotary switch and connect the test lead as shown above.

- c) Connect the test leads in series to the circuit to be measured
- d) Reconnect the power to the circuit to be measured and read the main display.
- e) Press c button to change the function. (in orders of $DC \rightarrow AC \rightarrow ac + dc)$

3. Measuring Resistance and Continuity Test

WARNING! Do not attempt to make resistance measurements or continuity test with circuit powered.

Measuring Range

11

ΟΗΜ : 50Ω, 500Ω, 5ΚΩ, 50ΚΩ, 500ΚΩ, 5ΜΩ, 50ΜΩ Conductance : 50nS Beep : 500Ω

Test Lead and Rotary Switch set-up

Rotary Switch	Black Test Lead	Red Test Lead
ns 4 Ω	COM	VΩ-¥Hz

- a) To measure the resistance, set up the rotary switch and the test lead as shown above.
- b) Connect the test leads to the resistor to be measured, and read the display.
- c) Press c button to change the function. (in orders of resistor \rightarrow conductance \rightarrow continuity test)
- d) To measure small resistance, any resistance in test leads should be removed. To do this, press button.

e) In continuity test, it beeps under 10(and stops over 602. f) The response time of continuity test is within 1mS g) Conductance is the opposite of resistance. The unit is

- Siemens (S).

4. Measuring Diode

CAUTION

Do not attempt to make diode measurements with circuit energized. The only way to accurately test a diode is to remove it completely from the circuit before attempting to measure it.

Measures forward voltage drop of a semiconductor like diodes or transistors. Working diode shows about 0.3~0.9V forward voltage drop. Shorted diode displays 0, opened diode displays" OFL".

Test Lead and Rotary Switch set-up

Rotary Switch	Black Test Lead	Red Test Lead
→	COM	VΩ -K Hz

- f) To measure the diode, set up the rotary switch and the test lead as shown above.
- g) Connect the test leads to the diode to be measured, and read the display.

5. Measuring Capacitance and Inductance

CAUTION!	Disconnect power to the circuits to be measured. Discharge the capacitor to
	be measured completely before attempting to measure.

Measuring Range

Capacitance : 5nF, 50nF, 500nF, 5uF, 50µF, 500µF, 5mF, 20mF Inductance : 50mH. 300mH

Test Lead and Rotary Switch set-up

Rotary Switch	Black Test Lead	Red Test Lead
*	COM	VΩ .K Hz
-Ur	COM	µmA-TEMP

- a) To measure the current, set up the rotary switch and
- the test lead as shown above. b) Connect the test leads to the circuit to be measured and read the display.
- c) Press C button to change the function. (in orders of capacitor -> coil)

- d) To remove any capacitance remained between the instrument and test leads in measuring small capacitance, press is button.
- 6. Measuring frequency and temperature Measuring Range Frequency : 50Hz, 500Hz, 5KHz, 50KHz, 500KHz, 5MHz Temperature : -50 - 1350 °C (-54 - 2462 °F)

Test Lead and Rotary Switch set-up

Rotary Switch	Black Test Lead	Red Test Lead
Hz	COM	VΩ-¥Hz
"C"F	COM	µmA-TEMP

a) Measuring frequency

- To measure the frequency, set up the rotary switch and the test lead as shown above.
- Connect the test leads to the circuit to be measured, and read the display.
- b) Measuring Temperature
- Connect the K type thermocouple adapter to COM (-) and wmammem (+) input.
- · Connect the K type probe and read the display.
- c) Press \bigcirc to change frequency to temperature. (in orders of frequency \rightarrow C \rightarrow F)
- 7. Using Adapters

Adapters

A254 (Current Adapter 10/60A) 100mV/A, 10mV/A A256 (Current Adapter 40/400A) 1mV/A A296 (Current Adapter 400/1000A) 1mV/A

Test Lead and Rotary Switch set-up

Rotary Switch	Black Test Lead	Red Test Lead	
Adp	COM		

- a) To measure the high current using the clamp adapter, set up the rotary switch and the test lead as shown above.
- b) To select the adapter, press we button. It is possible to read directly for A254 when the displays are 00.000A in 10A range, and 000.0A in 60A, for A256

& A296 when the displays are 0000.0A.

c) Measures the current with a clamp in the adapter

d) Press combutton to change the AC and DC current.

F. Additional Functions

- 1. Data Logging
 - a) Stores the measured value and its measured time in time intervals.
 - b) Depress estimation button for few seconds, it starts to store in time intervals as programmed in SETUP mode. At this time, IDE upper right hand side of LCD, and II with the stored quantity on lower left hand side will be displayed.
 - c) To finish the Logging, depress auton for few seconds, or reset the rotary switch.
 - d) To display the stored value, depress end button for few seconds. The first stored value with its address,
 and R will be displayed.
 - e) Use est and e buttons to see stored values by changing its addresses.
 - f) Stores up to 1000 values.
 - g) Automatic Power off can be programmed by user in SETUP mode.
- 2. Memory/Recall
 - a) To store the values manually and recall the values later.
 - b) Depress contained when the button was pressed will be stored in Memory. Its address and in will be displayed in the lower left hand side of the LCD.
 - c) Stores the value whenever end button is pressed.
 - d) To exit the Memory mode, reset the rotary switch or depress COMP button.
 - e) When goes back to Memory mode, it stores next to the last saved address. It saves in orders until user erases the data. (up to 100)
 - f) To display the measured value, depress we button for few seconds. To change the address, use we nd we buttons. (while in Memory or Logging mode, exit the each mode before starts Recall mode)

- g) To erase the stored value, 🐨 button for few seconds in Recall mode.
- 3. Relative
 - a) Measures the relative value that compares it to the reference value.
 - b) When press we without a side of LCD, and reference value in lower right hand side, % of compared value in lower left hand side will be displayed.
 - c) To exit REL mode, press is button again.
 - d) Changing the reference value

Press would be used and would be buttons to change the value. Use would and would buttons to change the decimal points.

- 4. Compare
 - a) Sets up the Low and High limit and compares the result as "HI"," PASS", and "LO".
 - b) Press even button. LOW value in lower left hand side and HIGH value in lower right hand side will be displayed.
 - c) Main display shows the compared value to LOW and HIGH
 - d) To exit the COMP mode, press ever button again.
 - e) To change the set up values, repeat the item d) in section 3. Relative.
- 5. Record
 - a) Calculates minimum, maximum and average of measured values and display.
 - b) Press essibutton. Main display shows the measuring value, while lower left hand side displays maximum, and right hand side displays minimum value.
 - c) Depress button for few seconds again, main display shows the average value. To goes back to measuring value, press REC button again
 - d) To exit the Record mode, depress es button again for few seconds.

6. Data Hold

- a) Stores a stable reading under 1 HOLD sub-display in the lower left hand side of the LCD. When a new stable reading is obtained, the reading under 1 HOLD will be moved to 2 HOLD in the lower right hand side and the new reading will be displayed under 1 HOLD.
- b) When no reading is obtained, the last measured value will be held.
- 7. Auto/Manual Range
 - a) Use when the user selects the measuring range
 - b) Press emoutton until the best range for the measurement selected
 - c) Depress even button for few seconds, it changes to Auto range
- 8. RS-232 Interface
- a) Transfers data directly to a computer or controls the instrument, and explains how to do.
- b) Communication Protocol
- · Baud Rate : 19200 Baud
- Parity : None
- Data Bit : 8 bit
- Stop Bit : 1 bit
- c) Transferring Format (from the instrument to a computer)
- " 1 b fun b sign Value b unit b sub1 b sub2 b crlf"
- " 2 b fun b sign Value b unit b crlf"
- " 3 b Keyname b control b crlf"
- fun : Function (DCV, ACV ..)
- b : Blank (0x20)
- sign : (0x2D) or + (0x2B)
- · value : Measured value
- unit : measured unit
- · sub1 : sub-display in lower left hand side of LCD
- sub-display in lower right hand side of LCD

16

- Keyname : Push button names
- Control : Status of button (ON or OFF)
- Cr : Carriage Return (0x0D)

- If : Line Feed (0x0A)
- d) Control Receiving Format (from a computer to the instrument)
- REC b OFF b crlf"
- Use to exit Record mode
- Send this command," REC b OFF b crlf" comes back.
- " REC b crlf

Change from average to measured value or vice versa in Record mode. When the instrument receives this command, it sends" REC b ON b crlf" or" REC b AVG b crlf"

" HOLD b crlf"

To on and off the Hold mode

When the instrument receives this command, it sends

- " HOLD b ON b crlf" of HOLD b OFF b crlf"
- " REL b crlf

To ON and OFF the Relative mode.

- When the instrument receives this command, it sends " REL b ON b RefValue b crif" or "REL b OFF b crif"
- RefValue is the reference value. • COMP b ON b Hv b Lv b crlf"

To activate Compare mode. Hv is high limit, Lv is low limit

" COMP b OFF b crlf

To exit Compare mode.

" RANGE b AUTO b crlf"." RANGE b UP b crlf",

" RANGE b DOWN b crlf"

To change the measuring range with Range control command. When the instrument receives this command, it sends "RANGE b AUTO b crlf" or "RANGE b MANUAL b crlf"

• YELLOW b crlf"

To use the mouthon.

• SKEY b REL b crlf"

To request of the status of espot to the instrument

* SKEY b REC b crlf"

To request of the status of me button to the instrument

" SKEY b HOLD b crlf"

17

To request of the status of embutton to the instrument

- " SKEY b COMP b crlf"
- To request of the status of eebutton to the instrument
- " SKEY b RANGE b crlf"

To request of the status of embutton to the instrument

DMM b GO b crlf"

When the instrument receives this command, it send out the measured values to Serial port.

" DMM b STOP b crlf"

When the instrument receives this command, it stops output.

" DMM b SINGLE b crlf"

When the instrument receives this command, it sends out one measured value at a time.

e) Communication Code

Rotary Switch Code

Code	Rotary Switch	
11	ACV	
10	DCV	
9	ADP	
8	mV	
7	Q	
6	Diode	
5	Capacitance	
4	Hz	
3	μΑ	
2	mA	
1	A	

Decimal Points Code

Code	Ω/Hz	V/A	CAP
0		753	5.00
1	50.000	50.000	50.0
2	500.00	500.00	500
3	5.0000	5.0000	5.00
4	50.000	50.000	50.0
5	500.00	500.00	500
6	5.0000	5000.0	5.00
7	50.000	8	50.0

Unit Code

Code	Unit
74	mV
2	V
3	V μA
4	mA
2 3 4 5 6	A
6	Adp
10	Ohm
11	Kohm
12	Mohm
13	Hz
14	Khz
15	Mhz
16	TempC
17	TempF
18	nF
19	μF
20	mF
21	nH
22	μH
23	mH
24	nS

G. Set up Mode

19

- * To activate the Set up Mode, press button then turn the power on
- * Press is button to change the mode.
- Int To set up the time intervals of the measured
- value. To select minutes and seconds, use COMP and REC buttons. To change the value, use REL and HOLD buttons. The preset value is 00:10
- To select the dB mode. REC button is for dBm,
- COMP button is for dBV. The preset value is dBm
- db
 To set up the reference value in dB mode. To select the position, use COMP and REC buttons.

 To change the value of the position, use REC and HOLD buttons. The preset value is 0600Ω
- To set up the time to off the back light. To select minutes and seconds, use COMP and REC buttons. To change the value, use REL and HOLD buttons. The preset value is 00:10

P. oFF	To select Auto Power Off function. Press REC to activate(En) the function, press COMP to
	deactivate(dIS). The preset value is En.
P. oFF	To select the Auto Power Off time. To select minutes and seconds, use COMP and REC buttons. To change the value, use REL and HOLD buttons. The preset value is 00:15.
hour . 0940	To set up the hours. To select minutes and seconds, use COMP and REC buttons. To change the value, use REL and HOLD buttons.
dRY 186	To change the date. To select month and date, use COMP and REC buttons. To change the value, use REL and HOLD buttons.
Fety ~	To change the year. To select the position to change use COMP and REC buttons. To change the value, use REL and HOLD buttons.
Fety "	To set up all values at preset values. Press REL% button for Yes, HOLD button for No. Except hour, date, month and year, all values will be set at preset values.
. Mainte	enance
WARNI	NG! Disconnect the power and remove all test leads before attempting to change battery or

- leads before attempting to change battery or fuse. Must use only fuses with correct current ratings and battery specified in this manual to avoid any damages or personal injury.
- 1. Cleaning
 - a) Please clean the case of the instrument regularly with mild detergent and a slightly damp cloth. Do not use an abradant.
 - b) When not use for a long time, please remove battery.
- 2. Fuse Replacement
 - a) Use correct volt fuse with correct current ratings only.b) Please refer to the specification in C-4 for the correct fuse type.
- 3. Battery Replacement
 - a) Use the battery only specified by the manufacturer.
- b) Please refer to the specification in C-4 for the correct battery type.

4. Battery

21

 [∧] "CAUTION : Danger of explosion if battery is incorrectly replaced. Replace only with the same or equivalent type recommended by the manufacturer. Dispose of used batteries according to the manufacturer's instructions."



Test Products International, Inc. 9615 SW Allen Blvd Beaverton, OR 97005-4814 USA Ph: 503-520-9197 Fax: 503-520-1225

Test Product International Ltd. 342 Bronte Street South, Unit 9 Milton, Ontario L9T 5B7 Ph: 905-693-8558 Fax: 905-693-0888

Test Products International Europe Ltd. Longley House, International Drive Crawley, West Sussex RH10 6AQ Ph. +44 (0) 1293 561212 Fax: +44 (0) 1293 813465

Copyright @ 2012, Test Products International. Inc.