

PRODUCT DISCONTINUATION

Business Unit	Product Line Code	Type of Change	Action	Date of issue
ICC	BE5	Discontinuation	Notify Distributors and Field	7/7/2014

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

Discontinuation of -LOE; -TP; -WW - articles due to low demand from the market and high maintenance costs for existing manufacturing equipment.

Warranty Information:

Stock Status

Can existing stock still be used? N

Is mixture of stock acceptable? N

Transaction Dates:

Last Buy from Phoenix Contact: 12/1/2014

Last Scheduled Ship from Phoenix Contact: 3/1/2015

PRODUCT DISCONTINUATION

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

ERIC JOHNSON
 ICC Lead Marketing Specialist
 (800)888-7388x3707
 ejohnson@phoenixcon.com

Thank you,



Bill Schalon, Product Marketing Manager

Discontinued Part#	Type Description	Replacement Part#	Type Description
3086021	UK 4-TP(2,4X0,8)L		
3086034	UK 4-TP(2,4X0,8)Q		
2773254	UKKB 3-TP(2,4X0,8)L		
2773267	UKKB 3-TP(2,4X0,8)Q		
3110117	MTK-WW(1X1)1		
3086076	UK 4-WW(1X1)		
2778013	UKK 3-LOER		
3014019	UK 4-LOER		
1405015	MBK-LOE		
2778097	UKK 3-LOER BU		
2017208	UHK 4-LOER/FS(10-2,8-0,8)		
3046016	UK 4-T-LOER-P/P		
3011012	UK 2,5-LOE/LOE		
1404016	MBK-LOE/LOE		
3013010	UK 2,5-LOER		
1405099	MBK-LOE BU		
0602482	LOEF		
1404090	MBK-LOE/LOE BU		