

### DESCRIPTION: BACKSHELL ASSEMBLY INSTRUCTIONS - METALIZED PLASTIC & PLASTIC



#### **ASSEMBLY INSTRUCTIONS:**

- 1. PREPARE CABLE AS REQUIRED TO ASSEMBLE TO THE CONNECTOR
- CHOOSE THE STRAIN RELIEF HALVES THAT MOST CLOSELY MATCH THE CABLE O/D AND PLACE ONE INTO EACH RECESS. THEY DO NOT NEED TO BE MATCHING HALVES
- 3. PLACE THE CABLE INTO THE STRAIN RELIEF IN ONE HALF OF THE PLASTIC HOOD. ENSURE THE CABLE IS PRESSED INTO THE STRAIN RELIEF PIECE
- 4. SNAP THE JACKSCREWS INTO POSITION
- 5. PLACE THE OTHER HALF OF THE PLASTIC HOOD INTO PLACE AND TIGHTEN TOGETHER WITH THE ASSEMBLY SCREWS AND NUTS


\*\*\*SEE PAGES 3 AND 4 FOR THE 50 POSITION DIE CAST ASSEMBLE INSTRUCTIONS\*\*\*



## RoHS COMPLIANT


# METALIZED PLASTIC AND PLASTIC


**BACKSHELL - 970 SERIES** 





CABLE WITHOUT SHIELD OR GROUND

Ø	THESE DRAWINGS AND SPECIFICATIONS ARE THE PROPERTY OF NorComp AND SHALL NOT BE REPRODUCED, COPIED OR USED AS THE BASIS FOR THE MANUFACTURE OF SALE OF APPARATUS WITHOUT WRITTEN PERMISSION.	DRAWN: C. SMITH		DATE:	03-20-06	
		CHECKED:		DATE:	Х	
NorComp		SCALE: N.T.S.	SHEET	0F <b>1</b>	4	REV 2
		DWG NO.	1			









### **DIE CAST**

4-25-12

### DO NOT SCALE FROM DRAWING



THESE DRAWINGS AND SPECIFICATIONS ARE THE PROPERTY OF NorComp AND SHALL NOT BE REPRODUCED, COPIED OR USED AS THE BASIS FOR THE MANUFACTURE OF SALE OF APPARATUS WITHOUT WRITTEN PERMISSION.

CHECKED:

DRAWN:

M. SIGMON DATE:

NorComp

SCALE: SHEET OF REV N.T.S. 2

DATE:

RoHS COMPLIANT

DWG NO. BACKSHELL - 970-050-030R121