



Date: APRIL 2018

Subject: Antenna EOL End Of Life/PCN Product Change Notice

Details of replacement parts, where available, are specified below. The change method details where small volume stocks of discontinued parts remain in stock. Orders for discontinued parts will be switched to replacement parts and notified at time of order.

Products Affected:

Part Number	Replacement	Change Method
ALPHA8/1M/FMEF/S/S/1	ALPHA8/1M/FMEF/S/S/11	When stock used up
Reason for change:	Manufacturing change	

Part Number	Replacement	Change Method
ALPHA8/1M/SMAM/S/S/1	ALPHA8/1M/SMAM/S/S/11	When stock used up
Reason for change:	Manufacturing change	

Part Number	Replacement	Change Method
ALPHA8/3M/FMEF/S/S/1	ALPHA8/3M/FMEF/S/S/11	When stock used up
Reason for change:	Manufacturing change	

Part Number	Replacement	Change Method
ALPHA8/3M/SMAM/S/S/1	ALPHA8/3M/SMAM/S/S/11	When stock used up
Reason for change:	Manufacturing change	

Part Number	Replacement	Change Method
ALPHA8/2.5M/FMEF/S/S/1	None but possible with volume demand	When stock used up
Reason for change:	Market Demand	

Part Number	Replacement	Change Method
ALPHA8/2.5M/SMAM/S/S/1	None but possible with volume demand	When stock used up
Reason for change:	Market Demand	

Part Number	Replacement	Change Method
ALPHA8/3M/MMCXM/S/RA/1	None but possible with volume demand	When stock used up
Reason for change:	Market Demand	

Part Number	Replacement	Change Method
DELTA8A/x/SMAM/S/S/17-V2	DELTA8A/x/SMAM/S/S/17	immediate
Reason for change:	Admin Error	

Part Number	Replacement	Change Method
ECHO1A/0.1M/GSC/S/S/11	None	When stock used up
Reason for change:	GSC Connector no longer made	

Part Number	Replacement	Change Method
ECHO1A/0.2M/GSC/S/S/11	None	immediate
Reason for change:	GSC Connector no longer made	

Part Number	Replacement	Change Method
ECHO2/0.14M/SMAM/S/S/1	None	immediate
Reason for change:	Market Demand - Custom Length not used	

Part Number	Replacement	Change Method
ECHO2/0.1M/GSC/S/S/1	None	immediate
Reason for change:	GSC Connector no longer made	

Part Number	Replacement	Change Method
ECHO2/0.2M/GSC/S/S/1	None	immediate
Reason for change:	GSC Connector no longer made	

Part Number	Replacement	Change Method
ECHO2/0.2M/SMAM/S/S/1	None	immediate
Reason for change:	Market Demand - SMA Connector on PCB designs are rare requirement	

Part Number	Replacement	Change Method
ECHO20A/0.5M/RG178/SMAM/RA/S/S/26	For direct client only	immediate
Reason for change:	Market Demand - Customer specific part	

Part Number	Replacement	Change Method
ECHO26/0.1M/IPEX/S/S/26	ECHO26A/0.1M/IPEX/S/S/15	When stock used up
Reason for change:	Production facility change	

Part Number	Replacement	Change Method
ECHO27/0.1M/IPEX/S/S/26	ECHO27/0.1M/IPEX/S/S/15	When stock used up
Reason for change:	Production facility change	

Part Number	Replacement	Change Method
OSCAR3B/x/NtypeF/S/S/17	none	immediate
Reason for change:	EOL 2014 – Admin Error Now remove from Price List	

Part Number	Replacement	Change Method
TANGO14/1M/LL/SMAM/S/S/22	TANGO14/1M/SMAM/S/S/22	immediate
Reason for change:	Market Demand - Low Loss superseded by Standard cable	

Part Number	Replacement	Change Method
TANGO14/5M/LL/SMAM/S/S/22	TANGO14/5M/SMAM/S/S/22	immediate
Reason for change:	Market Demand - Low Loss superseded by Standard cable	