



PROPER USE GUIDELINES

Cumulative Trauma Disorders can result from the prolonged use of manually powered hand tools. AMP hand tools are intended for occasional use and low volume applications. AMP offers a wide selection of powered application equipment for extended–use, production operations.



Figure 1

1. INTRODUCTION

AMP* Hand Crimping Tool 59528–1 is designed to crimp the AMP FASTON* terminals listed in Figure 2. Read these instructions thoroughly before using the hand tool.

NOTE

Measurements are in millimeters [followed by inch equivalents in brackets]. Figures and illustrations are for identification only and are not drawn to scale.

Reasons for reissue are in Section 6, REVISION SUMMARY.

2. DESCRIPTION

The hand tool features two fixed dies (crimpers), two movable dies (anvils), a locator/insulation stop, and a CERTI-CRIMP ratchet.

©1999 AMP Incorporated, Harrisburg, PA. All International Rights Reserved. *Trademark This controlled document is subject to change. For latest revision call the AMP FAX* number.

The locator/insulation stop positions the terminal between the crimping dies and aids in locating the wire in the terminal. In use, it rests in the terminal's locator slot.

The CERTI-CRIMP ratchet ensures full crimping of the terminal. Once engaged, the ratchet will not release until the tool handles have been FULLY closed.



The crimping dies bottom before the CERTI–CRIMP ratchet releases. This is a design feature that ensures maximum electrical and tensile performance of the crimp. Do NOT re–adjust the ratchet.

3. CRIMPING PROCEDURE

Refer to Figure 2 and select wire of the specified size and insulation diameter. Strip the wires to the length indicated. Do not cut or nick the wire strands.

Select an applicable terminal and identify the appropriate crimp section, according to the letter marking, on the BACK of the tool.



WIRE SIZE RANGE (AWG)	INSUL DIA RANGE	TERMINAL PART NUMBER		CRIMP SECT
		LP	STRIP	LETTER MARKING
24 to 22	1.02–1.52 [.040–.060]		42067–1 42415–1	A
22 to 18	1.52–2.54 [.060–.100]	42470–1	42068 60118–1 60197–1 60415–1 60577–1	В

Figure 2

1 of 4



Figure 3

Refer to Figure 3 and proceed as follows:

1. Hold tool so that the BACK side is facing you.

2. Make certain that the ratchet is released by squeezing the tool handles and allowing them to open FULLY.

3. Looking straight into the crimping dies from the BACK of the tool, insert a terminal (insulation barrel first) into the FRONT of the appropriate crimping section.

4. Position the terminal in the crimpers so that the locator/insulation stop enters the terminal locator slot.

5. Hold the terminal in this position and squeeze the tool handles until the insulation anvil starts entry into the insulation crimper.

CAUTION

Squeezing the handles together too much will deform the insulation barrel or wire barrel.

6. Insert a properly stripped wire through the locator wire slot and into the wire barrel of the terminal until the insulation butts against the locator/insulation stop.

7. Hold the wire in place, squeeze tool handles together FULLY. Open tool handles and remove crimped terminal.

4. MAINTENANCE AND INSPECTION PROCEDURE

AMP recommends that a maintenance and inspection program be performed periodically to ensure dependable and uniform terminations. Though recommendations call for at least one inspection a month, frequency of inspection depends on:

1. The care, amount of use, and handling of the hand tool.

2. The presence of abnormal amounts of dust and dirt.

3. The degree of operator skill.

4. Your own established standards.

The hand tool is inspected before being shipped; however, AMP recommends that the tool be inspected immediately upon arrival to ensure that the tool has not been damaged during shipment.

4.1. Daily Maintenance

1. Hand tool should be immersed (handles partially closed) in a reliable commercial degreasing compound to remove accumulated dirt, grease, and foreign matter. When degreasing compound is not available, tool may be wiped clean with a soft, lint-free cloth. Do NOT use hard or abrasive objects that could damage the tool.

2. Make certain that the retaining pins are in place and that they are secured with retaining rings.

3. All pins, pivot points, and bearing surfaces should be protected with a THIN coat of any good SAE 20 motor oil. Do not oil excessively.

4. When the tool is not in use, keep handles closed to prevent objects from becoming lodged in the crimping dies. Store the tool in a clean, dry area.

4.2. Periodic Inspection

A. Lubrication

Lubricate all pins, pivot points, and bearing surfaces with SAE 20 motor oil as follows:

Tool used in daily production – lubricate daily Tool used daily (occasional) – lubricate weekly Tool used weekly – lubricate monthly

Wipe excess oil from tool, particularly from crimping area. Oil transferred from the crimping area onto certain terminations may affect the electrical characteristics of an application.

B. Visual Inspection

1. Close tool handles until ratchet releases and then allow them to open freely. If they do not open quickly and fully, the spring is defective and must be replaced. See Section 5, REPLACEMENT AND REPAIR.

2. Inspect head assembly for worn, cracked, or broken dies. If damage is evident, return the tool to AMP for evaluation and repair. See Section 5, REPLACEMENT AND REPAIR.

C. Crimp Height Inspection

This inspection requires the use of a modified micrometer with a modified anvil and spindle, as shown in Figure 4. AMP recommends the Crimp Height Comparator RS-1019-5LP which can be purchased from:

Shearer Industrial Supply Co. 20 North Penn Street o York, PA 17401–1014	or	VALCO 1410 Stonewood Drive Bethlehem, PA 18017–3527
--	----	---

Proceed as follows:

1. Refer to the table in Figure 2 and select a terminal and a maximum size wire for each crimp section listed in the table.

2. Refer to Section 3, CRIMPING PROCEDURE, and crimp the terminal(s) accordingly.

3. Using a crimp height comparator, measure the wire barrel crimp height as shown in Figure 4. If the crimp height conforms to that height, the tool is considered dimensionally correct. If not, the tool must be returned to AMP for evaluation and repair. See Section 5, REPLACEMENT AND REPAIR.



TERMINAL NUMBER	CRIMP SECTION	WIRE SIZE (AWG) (Max)	CRIMP HEIGHT DIMENSION "A"
42067–1 42415–1	А	22	0.76 <u>+</u> 0.05 [.030 <u>+</u> .002]
42068 42470–1 60118–1 60197–1 60415–1 60577–1	В	18	1.14 <u>±</u> 0.05 [.045 <u>±</u> .002]

Figure 4

For additional information concerning the use of the crimp height comparator, refer to AMP instruction sheet 408–7424.

D. CERTI-CRIMP Ratchet Inspection

The CERTI-CRIMP ratchet feature on AMP hand tools should be checked to ensure that the ratchet does not release prematurely, allowing the dies to open before they have fully bottomed. Obtain a 0.025 [.001] shim that is suitable for checking the clearance between the bottoming surfaces of the crimping dies. Proceed as follows:

1. Select a terminal, maximum size wire, and the designated crimp section for the wire you are using. See Figure 2.

2. Position the terminal and wire between the crimping dies, as described in Section 3, CRIMPING PROCEDURE.

3. Hold the wire in place and squeeze the handles until the CERTI-CRIMP ratchet releases. Hold the handles in this position, maintaining just enough tension to keep the dies closed.

4. Check the clearance between the bottoming surfaces of the crimping dies. If the clearance is 0.025 [.001] or less, the ratchet is satisfactory. If clearance exceeds 0.025 [.001], the ratchet is out of adjustment and must be repaired. See Section 5, REPLACEMENT AND REPAIR.



Weight: 566 g [1 lb 4 oz]

REPLACEMENT PARTS						
ITEM	PART NUMBER	DESCRIPTION	QTY PER ASSY			
1	21045–3	RING, Retaining	4			
2	21045–9	RING, Retaining	2			

Figure 5

5. REPLACEMENT AND REPAIR

Replacement parts are listed in Figure 5. Parts other than those listed in Figure 5 should be replaced by AMP to ensure quality and reliability of the tool. Order replacement parts through your AMP representative, or call 1–800–526–5142, or send a facsimile of your purchase order to 1–717–986–7605, or write to:

CUSTOMER SERVICE (38–35) AMP INCORPORATED P.O. BOX 3608 HARRISBURG, PA 17105–3608 For tool repair service, please contact an AMP representative at 1-800-526-5136.

6. REVISION SUMMARY

Since the previous release of this sheet, the following changes were made:

Per EC 0990-0949-99

- Updated document to corporate requirements
- Changed document title
- Changed tool repair service information in Section 5, REPLACEMENT AND REPAIR