

PCN-BCA-001160

# **Product Change Notice**

Issue Date: November 1, 2018

#### Change Type:

Adding Assembly Production Site

### Parts Affected:

BCM65100IFEB BCM65100IFEBG BCM65100IFSBG BCM65100TIFEBG BCM65100TIFSBG BCM65112IFEBG BCM65112IFSBG BCM65112TIFEBG BCM65112TIFSBG BCM65116IFEBG BCM65116IFSBG BCM65116SIFEBG BCM65116TIFEBG BCM65116TIFSBG BCM65118IFEBG BCM65118IFSBG BCM65118KFEBG BCM65118TIFEBG BCM65118TIFSBG BCM65300IFEB BCM65300IFEBG BCM65300IFSBG BCM65300TIFEBG BCM65300TIFSBG BCM65308IFEBG

### Description and Extent of Change:

Adding Assembly Production site - Amkor Taiwan

### **Reasons for Change:**

Additional assembly capacity.

### Effect of Change on Fit, Form, Function, Quality, or Reliability:

The device specification will remain the same, which will ensure product electrical performance remains the same. Appropriate electrical characterization and reliability qualification will be performed on representative products to ensure normal parametric distribution, consistent electrical performance, and reliability.

### **Effective Date of Change:**

Product shipments using this change will begin after February 15, 2019. Timing of shipment of the changed part will vary by part number depending on qualification completion, customer demand, and inventory levels.



## **Qualification Data:**

TEST	SPEC	Conditions	Sample Size	Read point (hrs/cycles ~)	Results
uHAST	JESD22-A118	130°C, 85% RH, No bias (pre- con parts)	77	96 Hrs	Pass
тс	JESD22-A104	-55°C to 125°C air to air (pre-con parts)	77	500 cycles	Pass
				700 cycles	Pass
				1000 cycles	Pass
HTSL	JESD22-A103	Ta= 150°C.	77	500 Hrs	Pass
				1000 Hrs	Pass
MSL	JESD-A113	Level 4(30°C, 60%RH)	154	96 Hrs	Pass

## Software / Firmware Update:

No firmware or software change is needed.

Please contact your Broadcom Inc. field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.