

Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

<u>Change Type</u>

Software

Product Affected

Part Number	Description	Old Revision	New Revision
XPP1002000-02R	XPort Pro Extended SRAM, Extended Temperature, w/ Encryption, Evolution	F15	G15
	OS, RoHS - Bulk		
XPP100200S-02R	XPort Pro Extended SRAM, Extended Temperature, w/ Encryption, Evolution	F16	G16
	OS, RoHS - Sample		
XPPDK1000-EVO-02	XPORT PRO EVOLUTION DEVELOPMENT KIT WITH 16MB RAM, ROHS	E15	F15

Description and Extent of Change

Lantronix is pleased to announce the release of XPORT PRO Firmware version 6.0.0.1R2. This new firmware includes bug fixes.

BUG FIXES:

- Modem Mode +++AT handling
- Memory leak while doing SSL handshake
- Root certificate in cert chain during SSL handshake then a CA check out performed.
- Multidrop/tristate topology not working on both Serial Port 1 and 2
- Update copyright information to 2021
- By default SNMP need to disabled

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions is available for download from our website, <u>http://www.lantronix.com/support/downloads</u>.

Effect of Change on Fit, Form, or Function

Functional changes as noted above.

Effective Date of Change

The change will go into effect for the listed products built from July 05, 2021 onwards.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.

7535 Irvine Center Drive | Suite 100 Irvine, CA 92618 USA

800.526.8766

lantronix.com