

Product Discontinuation Notice

3M™ Platens for Mini Socket, 3442-45 and -46 Series

Issue Number: 909
Date: December 12, 2014

Product Discontinuance

Effective immediately, 3M is discontinuing the Platens for Mini Socket, viz.

1. 3442-45 Series (80-6200-9890-7) and
2. 3442-46 Series (80-6200-9891-5).

3M has developed an alternative platen that eliminates the need for two different tools. For this reason, there will be no last time buy.

Alternate Solution

3M™ Platen, 3442-9 Series (80-6100-3150-4) is the replacement for the discontinued platens. This is fully compatible with the 3M™ Locator Plate, 3443-113 Series used for assembling 3M™ Mini Sockets, 82000 Series.

Actions Required

1. Identify the parts on your database and revising their status as obsolete;
2. Contacting past users of the old Platens, advising them of this end-of-line announcement and of the availability of the new Platen, 3442-9 Series.

Contact Information

Lindsay Powell, Marketing Manager (Core Interconnect Products)
+1 512 984 6669, lpowell@3M.com

3M is a trademark of 3M Company.

Important Notice

All statements, technical information, and recommendations related to 3M's products are based on information believed to be reliable, but the accuracy or completeness is not guaranteed. Before using this product, you must evaluate it and determine if it is suitable for your intended application. You assume all risks and liability associated with such use. Any statements related to the product which are not contained in 3M's current publications, or any contrary statements contained on your purchase order shall have no force or effect unless expressly agreed upon, in writing, by an authorized officer of 3M.

Warranty; Limited Remedy; Limited Liability.

This product will be free from defects in material and manufacture for a period of one year from the time of purchase. **3M MAKES NO OTHER WARRANTIES INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.** If this product is defective within the warranty period stated above, your exclusive remedy shall be, at 3M's option, to replace or repair the 3M product or refund the purchase price of the 3M product. **Except where prohibited by law, 3M will not be liable for any indirect, special, incidental or consequential loss or damage arising from this 3M product, regardless of the legal theory asserted.**



Electronics Materials Solutions Division
Interconnect Products
6801 River Place Blvd.
Austin, TX 78726-9000
1-800-225-5373

www.3Mconnectors.com

© 3M 2014. All Rights Reserved.