

Product Change Notification - RMES-28TSFZ599

Date:

25 Jun 2019

Product Category:

Ethernet Switches

Affected CPNs:



Notification subject:

Data Sheet - VSC7420/21/22/23/24/25/26/27/28/29

Notification text:

Microchip has released a new DeviceDoc for the 7, 10, 11 Port PHYs and Ethernet Switches. If you are using one of these devices, please refer the document listed below.

Notification Status:

Final

Description of Change:

Design considerations were added to address issues with 1588 out-of-sync and copper ports. MIIM Interface in Slave Mode section was updated with a note.

" The MIIM slave I/F, due to its low bandwidth, is not aimed at supporting or recommended for managed switch applications. "

Below is the list of updated datasheets:

- 1. VSC7420-02, VSC7421-02, VSC7422-02 <u>VSC7420-02, VSC7421-02 and VSC7422-02 SparX-III</u> Datasheet
- 2. VSC7423-02 VSC7423-02 Datasheet
- 3. VSC7424-02, VSC7425-02, VSC7426-02, VSC7427-02 <u>VSC7424-02, VSC7425-02, VSC7426-02, VSC7427-02</u> and VSC7427-02 SparX-III Datasheet
- 4. VSC7428-12 VSC7428-12 Datasheet
- 5. VSC7428-02_VSC7429-02 <u>VSC7428-02 and VSC7429-02 Caracal Datasheet</u>

Impacts to Data Sheet:

None

Reason for Change:

To Improve Manufacturability

Change Implementation Status:

Complete

Date Document Changes Effective:

25 June 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices:

N/A

Attachment(s):

Please contact your local <u>Microchip sales office</u> with questions or concerns regarding this notification.



Terms and Conditions:

If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our <u>PCN home page</u> select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the <u>PCN FAQ</u> section.

If you wish to <u>change your PCN profile</u>, <u>including opt out</u>, please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

VSC7420XJG-02

VSC7420XJQ-02

VSC7421XJG-02

VSC7421XJQ-02

VSC7422XJG-02

VSC7422XJQ-02

VSC7423XJG-02

VSC7424XJG-02

VSC7425XJG-02

VSC7426XJG-02

VSC7427XJG-02

VSC7428XJG-02

VSC7428XJG-12

VSC7429XJG-02