

PRODUCT DISCONTINUATION

#PD-IF-UFCG-15

Business Unit	Product Line Code	Type of Change	Action	Date of issue
IF	CK1	Discontinuation	Notify Distributors and Field	12/23/2015

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

Shortage of component

Warranty Information:

Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? N

Transaction Dates:

Last Buy from Phoenix Contact: Until stock quantity is zero.

Last Scheduled Ship from Phoenix Contact: Until stock quantity is zero.

PRODUCT DISCONTINUATION

Previous Product	(if applicable)	New Product
<p data-bbox="203 436 743 468">MINI MCR-SL-TC-UI-NC p-n 2864299</p> 		<p data-bbox="933 436 1364 468">MINI MCR-TC-UI p-n 2902851</p> 
<p data-bbox="235 957 711 989">MINI MCR-SL-TC-UI p-n 2864448</p> 		<p data-bbox="901 957 1396 989">MINI MCR-2-TC-UI-C p-n 2902053</p> 

Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Derek Sackett
DSACKETT@PHOENIXCON.COM

Thank you,

PRODUCT DISCONTINUATION

Derek Sackett

Derek Sackett, Product Marketing Manager

Discontinued Part#	Type Description	Replacement Part#	Type Description
2864299	MINI MCR-SL-TC-UI-NC	2902851 or 2902055	MINI MCR-TC-UI-NC or MINI MCR-2-TC-UI
2864448	MINI MCR-SL-TC-UI	2902053	MINI MCR-2-TC-UI-C