

PRODUCT CHANGE NOTIFICATION

Product Category COPPER - CABLE - 1G 20200217-1

Product Group COPPER - CABLE - 1G

ISSUE DATE: 20200217

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Some Copper Cable parts are being discontinued in order to streamline the product offering (PUC6c04 and NUC6c04). Please see the Product Change Notification for a list of affected items.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2020	2	17
Old product discontinuation date*	2020	2	17

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned within 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience Manager if you have any questions.

IMPACTED PART NUMBER(s)	Type	Replacement Part 1
PUC6C04BL-C	Direct Replacement	PUC6C04BL-FE
PUC6C04BU-C	Direct Replacement	PUC6C04BU-FE
PUC6C04GR-C	Direct Replacement	PUC6C04GR-FE
PUC6C04IG-C	Direct Replacement	PUC6C04IG-FE
PUC6C04RD-C	Direct Replacement	PUC6C04RD-FE
PUC6C04OR-C	Direct Replacement	PUC6C04OR-FE
PUC6C04VL-C	Direct Replacement	PUC6C04VL-FE
PUC6C04WH-C	Direct Replacement	PUC6C04WH-FE
PUC6C04YL-C	Direct Replacement	PUC6C04YL-FE
PUC6C04PB-C	No Replacement	
PUC6C04PG-C	No Replacement	
PUC6C04BL-CE	Direct Replacement	PUC6C04BL-FE
PUC6C04BU-CE	Direct Replacement	PUC6C04BU-FE
PUC6C04GR-CE	Direct Replacement	PUC6C04GR-FE
PUC6C04IG-CE	Direct Replacement	PUC6C04IG-FE
PUC6C04RD-CE	Direct Replacement	PUC6C04RD-FE
PUC6C04OR-CE	Direct Replacement	PUC6C04OR-FE
PUC6C04VL-CE	Direct Replacement	PUC6C04VL-FE
PUC6C04WH-CE	Direct Replacement	PUC6C04WH-FE
PUC6C04YL-CE	Direct Replacement	PUC6C04YL-FE
PUC6C04IG-CE-S	No Replacement	
NUC6C04BL-C	Direct Replacement	NUC6C04BL-FE
NUC6C04BU-C	Direct Replacement	NUC6C04BU-FE
NUC6C04IG-C	Direct Replacement	NUC6C04IG-FE
NUC6C04GR-C	Direct Replacement	NUC6C04GR-FE
NUC6C04RD-C	Direct Replacement	NUC6C04RD-FE
NUC6C04OR-C	Direct Replacement	NUC6C04OR-FE
NUC6C04VL-C	Direct Replacement	NUC6C04VL-FE
NUC6C04WH-C	Direct Replacement	NUC6C04WH-FE
NUC6C04YL-C	Direct Replacement	NUC6C04YL-FE
NUC6C04BL-CE	Direct Replacement	NUC6C04BL-FE
NUC6C04BU-CE	Direct Replacement	NUC6C04BU-FE
NUC6C04IG-CE	Direct Replacement	NUC6C04IG-FE
NUC6C04GR-CE	Direct Replacement	NUC6C04GR-FE
NUC6C04RD-CE	Direct Replacement	NUC6C04RD-FE
NUC6C04OR-CE	Direct Replacement	NUC6C04OR-FE
NUC6C04VL-CE	Direct Replacement	NUC6C04VL-FE
NUC6C04WH-CE	Direct Replacement	NUC6C04WH-FE
NUC6C04YL-CE	Direct Replacement	NUC6C04YL-FE
NUC6C04BU-CE-S	No Replacement	