u·p·t·o·d·a·t·e Newsletter 🐼 DK

November 29, 2019

## Product Information Updated CSA marking for EPCOS varistors

Due to updated CSA standard, the marking will be changed on EPCOS varistors and labels that are produced from October 1, 2019.

Affected are the B721\*, B722\*, B723\* and B726\* series of varistors.

For an interim period shipments can include varistors with old and new markings.

## Affected products

Ordering code	Marking on varistor	Marking on label
B72107*		
B72110*		
B72114*		$\checkmark$
B72120*		
B72205S*/U*		
B72207S*/U*		
B72210S*/P*/U*/X*		
B72214S*/P*/U*/X*/Q*/T*/F*		
B72220S*/P*/U*/X*/Q*/T*		
B72225*		
B72232B*/M*		
B72240B*/L*/M*		
B72241L*/M*		
B72242L*/M*		
B72250L*		
B72260B*		
B72280B*		
B723*		
B72650*		
B72660*		

This change will have no effects on form, fit, function, quality, reliability and lead-times of the affected products.

Varistors, CeraDiodes Internal / External

191129VAR1e

## u·p·t·o·d·a·t·e Newsletter

November 29, 2019

## Change of marking

CSA marking on varistors		
Current	New	
SP.		

CSA marking on labels		
Current	New	
<b>SP</b> ®	<b>€</b> ₽	

Contact Anthony Yu, PPD VAR PM, Zhuhai

Customers are asked to address inquiries directly to their sales contacts.