

Product/Process Change Notifications

Amphenol Commerical Products

PCN - 22 109

www.amphenol-cs.com			Release Date:	October	12	2022
599 - MICRO	OSPACE					
599-57UF-MINITEK MICROSPACE 1.8						
Dorian MOYNE						
Notification of Change with Immediate Effectivity						
Affected customers						
Location Change						
Assembly location change from Amphenol Site at Besancon, France to Nantong, China						
In order to reduce the lead time and to increase our serviceability level. Only the assembly process relocated, and the product performance and quality will remain the same.						
10142961-004LF						
15 November ,2022						
NA						
NA						
12 October ,2022						
Contact your local Amphenol Representative, or Product Manager						
Dorian MOYNE / Product Manager						
0						
	599-57UF-M Dorian MOY Notification of Affected cus Location Cha Assembly loo In order to re relocated, ar 10142961-00 15 Nov 15 Nov NA NA NA 12 O Contact your Dorian MOY	Dorian MOYNE Notification of Change with Imm Affected customers Location Change Assembly location change from In order to reduce the lead time relocated, and the product perform 10142961-004LF 15 November ,2022 NA 12 October ,2022 Contact your local Amphenol Report Dorian MOYNE / Product Mana	599-57UF-MINITEK MICROSPACE 1.8 Dorian MOYNE Notification of Change with Immediate Effectivity Affected customers Location Change Assembly location change from Amphenol Site at Besa In order to reduce the lead time and to increase our ser relocated, and the product performance and quality will 10142961-004LF 15 November ,2022 NA NA NA 12 October ,2022 Contact your local Amphenol Representative, or Product Dorian MOYNE / Product Manager	599 - MICROSPACE 599-57UF-MINITEK MICROSPACE 1.8 Dorian MOYNE Notification of Change with Immediate Effectivity Affected customers Location Change Assembly location change from Amphenol Site at Besancon, France to Ni In order to reduce the lead time and to increase our serviceability level. O relocated, and the product performance and quality will remain the same. 10142961-004LF 15 November ,2022 NA NA 12 October ,2022 Contact your local Amphenol Representative, or Product Manager Dorian MOYNE / Product Manager	599 - MICROSPACE 599 - STUF-MINITEK MICROSPACE 1.8 Dorian MOYNE Notification of Change with Immediate Effectivity Affected customers Location Change Assembly location change from Amphenol Site at Besancon, France to Nantong, China In order to reduce the lead time and to increase our serviceability level. Only the asser relocated, and the product performance and quality will remain the same. 10142961-004LF 15 November ,2022 NA NA 12 October ,2022 Contact your local Amphenol Representative, or Product Manager Dorian MOYNE / Product Manager	599 - MICROSPACE 599-57UF-MINITEK MICROSPACE 1.8 Dorian MOYNE Notification of Change with Immediate Effectivity Affected customers Location Change Assembly location change from Amphenol Site at Besancon, France to Nantong, China In order to reduce the lead time and to increase our serviceability level. Only the assembly prorelocated, and the product performance and quality will remain the same. 10142961-004LF 15 November ,2022 12 October ,2022 Contact your local Amphenol Representative, or Product Manager Dorian MO YNE / Product Manager

Note:

Customers should contact Product Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .