



RO HM CO., LTD.

Date: December 10<sup>th</sup>, 2014

Notice of product discontinuation

On behalf of ROHM, we would like to take this opportunity to thank you for doing business with us.

This notice is to inform you that the manufacturing of the products listed below has come to an end of life.

Thank you very much for your attention and we appreciate your understanding and cooperation.

EOL PN	Replacement PN
BU97930MUV-BZE2	BU97930MUV-E2
BU97931FV-BZE2	BU97931FV-E2
BU97981KV-BZE2	BU97981KV-E2
BU9795AKV-BZE2	BU9795AKV-E2
BU9794AKV-BZE2	BU9794AKV-E2
BU9799KV-BZE2	BU9799KV-E2
BU97950FUV-BZE2	BU97950FUV-E2
BD9355MWV-BZE2	BD9355MWV-E2
BD9639MWV-BZE2	BD9639MWV-E2

"The replacement parts are the same fit, form, and function of the part number listed as EOL."

Date Operations  
12-10-2014