



Spec No. :DS86-2016-0062 Effective Date: 02/03/2017 Revision: -

LITE-ON DCC

RELEASE

BNS-OD-FC001/A4

LITE-ON Technology Corp. / Optoelectronics No.90,Chien 1 Road, Chung Ho, New Taipei City 23585, Taiwan, R.O.C. Tel: 886-2-2222-6181 Fax: 886-2-2221-1948 / 886-2-2221-0660 http://www.liteon.com/opto



Data Sheet Optical Sensor

1. Description

The LTR-578ALS-02 is an integrated low voltage I2C ambient light sensor (ALS), and proximity sensor (PS), with built-in emitter in a single miniature chipled lead-free surface mount package.

The ALS provides a linear response over a wide dynamic range, which is well suited to applications under very low or bright ambient brightness. Besides, with built-in proximity sensor, this sensor offers the feature to detect object at a user configurable distance.

The sensor has a programmable interrupt with hysteresis to response to events and that removes the need to poll the sensor for a reading which improves system efficiency. This CMOS design and factory-set one time trimming capability ensure minimal sensor-to-sensor variations for ease of manufacturability to the end customers.

2. Features

- I²C interface (Standard mode @100kHz or Fast mode @400kHz)
- Ambient Light and Proximity Sensing in one ultra-small ChipLED package
- Very low power consumption with sleep mode capability
- Operating voltage ranges: 1.7V to 3.6V
- Operating temperature ranges: -40 to +85 °C
- Built-in temperature compensation circuit
- Programmable interrupt function for ALS and PS with upper and lower thresholds
- RoHS and Halogen free compliant

ALS Features

- > 16 to 20 bits effective resolution
- > Wide dynamic range with linear response
- > Close to human eye spectral response
- > Automatic rejection for 50Hz/60Hz lighting flicker

PS Features

- Built-in LED driver and detector
- > High ambient light suppression
- > 8, 9, 10, 11-bit(selectable) effective resolution
- Cancellation of crosstalk
- Programmable LED drive settings



Optical Sensor LTR-578ALS-02

3. Applications

- Control brightness of display panel
- Object detection in mobile, computing, and consumer devices.

4. Ordering Information

Part Number	Packaging Type	Package	Quantity
LTR-578ALS-02	Tape and Reel	8-pin chipled package	8000

5. Outline Dimensions









Note: 1. All dimension in millimeter.

2. All dimension tolerance is 0.2mm unless specified.

2/40

Part No. : LTR-578ALS-02 BNS-OD-FC002/A4



Data Sheet Optical Sensor LTR-578ALS-02

6. Functional Block Diagram

LTR-578ALS-02 contains 2 photodiodes (Visible and IR diode) for respective photocurrent measurement. The photodiode currents are converted to digital values by ADCs. The sensor also included an emitter LED, as well as some peripheral circuits such as an internal oscillator, a current source, voltage reference, and internal fuses to store trimming information.







Optical Sensor LTR-578ALS-02

7. Application Circuit



Note: It is a must that VDD and VLED to be separated.

I/O Pins Configuration Table

Pin	I/О Туре	Symbol	Description
1	IN/OUT	SDA	I²C serial data
2	OUT	INT	Interrupt
3	OUT	LDR	Connect to LED Cathode
4	OUT	LEDK	LED Cathode. Connect to LDR pin if internal LED driver circuit is used
5	IN	LEDA	LED Anode.
6	Ground	GND	Ground
7	IN	SCL	I ² C serial clock
8	Supply	VDD	Power Supply Voltage

Recommended Application Circuit Components

Component	Recommended Value
Rp1, Rp2, Rp3 [1]	1 k Ω to 10 k Ω
C1, C3	1uF ±20%, X7R / X5R Ceramic
C2	0.1uF

[1] Selection of pull-up resistors value is dependent on bus capacitance values. For more details, please refer to I²C Specifications: http://www.nxp.com/documents/user_manual/UM10204.pdf

4/4(



Optical Sensor LTR-578ALS-02

8. Ratings and Specifications

Absolute Maximum Ratings at Ta = 25°C

Parameter	Symbol	Min.	Мах	Unit
Supply Voltage	VDD		4.0	V
Digital Voltage Range	SCL, SDA, INT	-0.5	4.0	V
Max Voltage Range	LDR	-0.5	4.0	V
Storage Temperature	T _{stg}	-40	100	°C
Electrostatic Discharge Protection	M		2000	V
(Human Body Model JESD22-A114)	V _{HBM}		2000	v

Note: Exceeding these ratings could cause damage to the sensor. All voltages are with respect to ground. Currents are positive into, negative out of the specified terminal.

Recommended Operating Conditions

Description	Symbol	Min.	Тур.	Max.	Unit
Supply Voltage	VDD	1.7		3.6	V
LED Supply Voltage	V _{LED}	2.3		4.5	V
Interface signal input high	V _{I2Chigh}	1.5		VDD	V
Interface signal input low	V _{I2Clow}	0		0.4	V
Operating Temperature	T _{ope}	-40		85	°C

Electrical & Optical Specifications

All specifications are at VDD = 2.8V, $T_{ope} = 25^{\circ}C$, unless otherwise noted.

Parameter	Min.	Тур.	Max.	Unit	Condition
Supply Current		150	260	uA	Active mode
ALS Active Supply Current		110		uA	Max. duty cycle, Vdd=2.8V, Gain3
PS Active Supply Current		95		uA	Max. duty cycle, Vdd=2.8V
Standby Current		1		uA	Shutdown Mode
Wakeup Time from Standby	5		10	ms	From Standby to Active mode
		5		115	where measurement can start



Optical Sensor LTR-578ALS-02

Characteristics Ambient Light

Parameter	Min.	Тур.	Max.	Unit	Condition
ALS Resolution	16		20	Bit	Programmable for 16, 17, 18, 19, 20 Bit
ALS Lux accuracy	-10		+10	%	
Dark Level Count		0	5	Count	0 Lux, 18-bit resolution
Min. Integration time	50		400	ms	With 50/60Hz Rejection
50/60 Hz flicker noise error	-5		+5	%	

Characteristics Proximity Sensor

Parameter	Min.	Тур.	Max.	Unit	Condition
PS Resolution	8		11	Bit	
Sensitivity Range		940		nm	
Detection Distance		10		cm	No window, 32 pulses, 60kHz, 100mA, 18% Gray Card
LED Pulse Current	2.5		125	mA	Configurable for 2.5,5,10,25,50,75,100 & 125mA
LED Pulse Frequency	60		100	kHz	
LED Duty Cycle		50		%	
Number of LED Pulses	1		255	Pulses	
Ambient Light Suppression			100	klux	Direct sunlight





Optical Sensor LTR-578ALS-02

Typical Device Parameter

(VDD = 2.8V, Ta=25℃, Default power-up settings, un less otherwise noted)



7/4(



Optical Sensor LTR-578ALS-02

AC Electrical Characteristics

All specifications are at VBus = 1.7V, T_{ope} = 25°C, unless otherwise noted.

Parameter	Symbol	Min.	Max.	Unit
SCL clock frequency	$f_{\rm SCL}$	1	400	kHz
Bus free time between a STOP and START condition	t _{BUF}	1.3		us
Hold time (repeated) START condition. After this period, the first clock pulse is generated	$t_{HD;STA}$	0.6		US
LOW period of the SCL clock	t _{LOW}	1.3		us
HIGH period of the SCL clock	t _{HIGH}	0.6		us
Set-up time for a repeated START condition	$t_{SU;STA}$	0.6		us
Set-up time for STOP condition	$t_{SU;STO}$	0.6		us
Rise time of both SDA and SCL signals	t _r	30	300	ns
Fall time of both SDA and SCL signals	t_f	30	300	ns
Data hold time	$t_{HD;DAT}$	0.3	0.9	us
Data setup time	$t_{SU;DAT}$	100		ns
Pulse width of spikes which must be suppressed by the input filter	t _{sP}	0	50	ns



Definition of timing for I²C bus

8/40



Optical Sensor LTR-578ALS-02

9. Principles of Operation

I²C Protocols

• I²C Write Protocol (type 1):



· I²C Write Protocol (type 2):



· I²C Read Protocol:



Part No. : LTR-578ALS-02 BNS-OD-FC002/A4

Data Sheet

Optical Sensor LTR-578ALS-02

· I²C Read (Combined format) Protocol:



I2C Slave Address

The 7 bits slave address for this sensor is 0x53H. A read/write bit should be appended to the slave address by the master device to properly communicate with the sensor.

	I ² C Slave Address										
Command	Command (0x53H) W							W/R			
Туре	Bit7	Bit6	Bit5	Bit4	Bit3	Bit2	Bit1	Bit0	value		
Write	1	0	1	0	0	1	1	0	0xA6H		
Read	1	0	1	0	0	1	1	1	0xA7H		





Optical Sensor LTR-578ALS-02

Register Set

Addr	R/W	Register Name	Description	Reset Value
0x00	RW	MAIN_CTRL	ALS, PS operation mode control, SW reset	0x00
0x01	R/W	PS_LED	PS LED settings	0x36
0x02	R/W	PS_PULSES	PS number of LED pulses	0x08
0x03	R/W	PS_MEAS_RATE	PS measurement rate in active mode	0x45
0x04	R/W	ALS_MEAS_RATE	ALS measurement rate and resolution in Active Mode	0x22
0x05	R/W	ALS_GAIN	ALS analog Gain	0x01
0x06	R	PART_ID	Part number ID and revision ID	0xB1
0x07	R	MAIN_STATUS	Power-On status, Interrupt status, Data status	0x20
0x08	R	PS_DATA_0	PS measurement data, least significant bits	0x00
0x09	R	PS_DATA_1	PS measurement data, most significant bits, and overflow	0x00
0x0D	R	ALS_DATA_0	ALS ADC measurement data, LSB	0x00
0x0E	R	ALS_DATA_1	ALS ADC measurement data	0x00
0x0F	R	ALS_DATA_2	ALS ADC measurement data, MSB	0x00
0x19	R/W	INT_CFG	Interrupt configuration	0x10
0x1A	R/W	INT_PST	Interrupt persist setting	0x00
0x1B	R/W	PS_THRES_UP_0	PS interrupt upper threshold, LSB	0xFF
0x1C	R/W	PS_THRES_UP_1	PS interrupt upper threshold, MSB	0x07
0x1D	R/W	PS_THRES_LOW_0	PS interrupt lower threshold, LSB	0x00
0x1E	R/W	PS_THRES_LOW_1	PS interrupt lower threshold, MSB	0x00
0x1F	R/W	PS_CAN_0	PS intelligent cancellation level setting, LSB	0x00
0x20	R/W	PS_CAN_1	PS intelligent cancellation level setting, MSB	0x00
0x21	R/W	ALS_THRES_UP_0	ALS interrupt upper threshold, LSB	0xFF
0x22	R/W	ALS_THRES_UP_1	ALS interrupt upper threshold, intervening bits	0xFF
0x23	R/W	ALS_THRES_UP_2	ALS interrupt upper threshold, MSB	0x0F
0x24	R/W	ALS_THRES_LOW_0	ALS interrupt lower threshold, LSB	0x00
0x25	R/W	ALS_THRES_LOW_1	ALS interrupt lower threshold, intervening bits	0x00
0x26	R/W	ALS_THRES_LOW_2	ALS interrupt lower threshold, MSB	0x00



Optical Sensor LTR-578ALS-02

MAIN_CTRL Register (0x00) (Read/Write)

This register controls the operation modes of ALS, which can be set to either standby or active mode. When writing to this register, it will cause a stop to any ongoing measurements (both ALS and PS) and start new measurement.

0x00	MAIN_CTRL (default = 0x00)									
	B7	B6	В5	B4	В3	B2	B1	В0		
	Reserved		Software Reset	Reserved	Reserved	ALS Enable	PS Enable			

Field	Bits	Default	Description		
Reserved	7:5	000			
SW Reset	4	0	0	Software reset is NOT triggered (default)	
SW Reset	4	0	1	Software reset is triggered	
Reserved	2:3	00			
ALS Enable	1	0	0	ALS standby(default)	
ALS ETIADIE	I	0	1	ALS active	
PS Enable	0	0 0		PS standby(default)	
			1	PS active	





Optical Sensor LTR-578ALS-02

PS_LED Register (0x01) (Read/Write)

This register controls the LED driving current and the LED pulse modulation frequency.

0x01		PS_LED (default = 0x36)							
	B7	B7 B6 B5 B4 B3 B2 B1 B0							
	Reserved	LED Pulse	e Modulation F	Frequency	Reserved		LED Current		

Field	Bits	Default	Descriptio	n
Reserved	7	0	-	-
			000	Reserved
			001	Reserved
			010	Reserved
LED pulse modulation	4:6	011	011	LED pulse period = 60kHz(default)
	4.0		100	LED pulse period = 70kHz
riequency	Frequency		101	LED pulse period = 80kHz
		110	LED pulse period = 90kHz	
			111	LED pulse period = 100kHz
Reserved	3	0	-	-
			000	LED pulsed current level = 2.5mA
			001	LED pulsed current level = 5.0mA
			010	LED pulsed current level = 10mA
LED current	0.0	110	011	LED pulsed current level = 25mA
LED current	2:0	110	100	LED pulsed current level = 50mA
			101	LED pulsed current level = 75mA
			110	LED pulsed current level = 100mA (default)
			111	LED pulsed current level = 125mA



Optical Sensor LTR-578ALS-02

PS_PULSES Register (0x02) (Read/Write)

This register controls number of PS LED pulses emitted.

0x02		PS_PULSES (default = 0x08)							
	B7	B7 B6 B5 B4 B3 B2 B1 B0							
				Number of L	.ED Pulses				

Field	Bits	Default	Description		
			00 0000	0 pulse (no light emission)	
			00 0001	1 pulse	
Number			00 0010	2 pulses	
Number of	-				
LED	7:0	0000 1000	00 1000	8 pulses (default)	
pulses					
			10 0000	32 pulses	
			1111 1111	255 pulses	

PS_MEAS_RATE Register (0x03) (Read/Write)

This register controls the timing of the periodic measurements of the PS during active mode. When the measurement rate is programmed to be faster than possible for the programmed ADC measurement, the rate will be lowered than programmed (maximum speed).

0x03		PS_MEAS_RATE (default = 0x45)							
	B7	B7 B6 B5 B4 B3 B2 B1 B0							
	0	1	0		lution/Bit dth	PS M	easurement	Rate	



Optical Sensor LTR-578ALS-02

Field	Bits	Default	Description		
Reserved	7:5	010	Must write	010	
50			00	8 bit(default)	
PS	1.0		01	9 bit	
Resolution/Bit	4:3	00	10	10 bit	
Width	dth	11	11 bit		
			000	Reserved	
			001	6.25ms	
DO			010	12.5ms	
PS	0.0	101	011	25 ms	
Measurement	2:0	101	100	50ms	
Kale	Rate		101	100ms(default)	
			110	200ms	
			111	400ms	

ALS_MEAS_RATE Register (0x04) (Read/Write)

This register controls ALS measurement resolution, Gain setting and measurement rate. When the measurement rate is programmed to be faster than possible for the programmed ADC measurement, the rate will be lowered than programmed (maximum speed).

0x04		ALS _MEAS_RATE (default = 0x22)							
	B7	B6	В5	B4	В3	B2	B1	В0	
	Reserved	ALS/C	Resolution/B	Bit Width	Reserved	ALSN	leasurement	Rate	

Field	Bits	Default	Description	
Reserved	7	0		
ALS Resolution		010	000	20 Bit, Conversion time = 400ms
ALS Resolution	6:4	010	001	19 Bit, Conversion time = 200ms

15/40



Optical Sensor LTR-578ALS-02

			010	18 Bit, Conversion time = 100ms(default)
			011	17 Bit, Conversion time = 50ms
			100	16 Bit, Conversion time = 25ms
			101/110/111	Reserved
Reserved	3	0		
			000	25ms
			001	50ms
ALS Measurement	2:0	010	010	100ms (default)
Rate	2.0	010	011	500ms
Nale	Nate		101	1000ms
			110/111	2000ms

ALS_GAIN Register (0x05) (Read/Write)

This register controls ALS measurement Gain Range.

0x05		ALS_GAIN (default = 0x01)							
	B7	B7 B6 B5 B4 B3 B2 B1 B0							
			Reserved			AL	.S Gain Rang	le	

Field	Bits	Default	Description		
Reserved	7:3	00000			
			000	Gain Range: 1	
			001	Gain Range: 3 (default)	
ALS Gain Range	2:0	:0 001	010	Gain Range: 6	
	Trange		011	Gain Range: 9	
			100	Gain Range: 18	



Optical Sensor LTR-578ALS-02

PART_ID Register (0x06) (Read Only)

This register defines the part number and revision identification of the sensor.

0x06		PART_ID (default = 0xB1)							
	B7	B7 B6 B5 B4 B3 B2 B1 B0							
		Part Nu	mber ID		Revision ID				

Field	Bits	Default	Description	
Part Number ID	7:4	1011	Part Number ID	
Revision ID	3:0	0001	Revision ID	

MAIN_STATUS Register (0x07) (Read Only)

This register stores the information about the ALS and PS interrupts and data status. The interrupt status in Bit 4 and Bit 1 determines if the ALS and PS interrupt criteria are met in Normal Interrupt Mode. It triggers when the ALS and/or PS data is above the upper or below the lower threshold for a specified number of consecutive measurements in respective interrupt persist settings. This register also provides PS logic signal status, which is used for indicating whether the detected object is near (PS data larger than PS upper threshold settings) or far (PS data smaller than PS lower threshold settings). For details interrupt behavior, refer to Section 10.

0x07		MAIN_STATUS (default = 0x20)								
	B7	B6	В5	B4	B3	B2	B1	В0		
	Reserved		Power ON Status	ALS Interrupt Status	ALS Data Status	PS Logic Signal Status	PS Interrupt Status	PS Data Status		

Field	Bits	Default	Description		
Reserved	7:6	00			

17/40



Optical Sensor LTR-578ALS-02

Power On Status	5	0	0	Power on event and All interrupt threshold settings in the registers have been rest to power on default states (either due to part turned on or power supply voltage glitch). Flag is cleared after read.
ALS	4	0	0	Interrupt is NOT triggered (default)
Interrupt Status	4	0	1	Interrupt is triggered and will be cleared after read
ALS Data			0	ALS data is old data (Data has been read)
Status	3	0	1	ALS data is new data (Data has not been read and will be cleared after read)
PS Logic			0	Object is far (default)
Signal Status	2	0	1	Object is near
PS	1	0	0	Interrupt is NOT triggered (default)
Interrupt Status	1	0	1	Interrupt is triggered and will be cleared after read
PS Data			0	PS data is old data (Data has been read)
Status	0	0	1	PS data is new data (Data has not been read and will be cleared after read)

PS_DATA Register (0x08 / 0x09) (Read Only)

The PS ADC channel data are expressed as an 11-bit data spread over 2 registers. The PS_DATA_0 and PS_DATA_1 registers provide the lower and upper byte respectively. An overflow bit is available to check if the PS data overflows. When I2C read operation is active and points to any of the register address between 0x07 and 0x18, both registers PS_DATA_0 and PS_DATA_1 will be locked until the I2C read operation has been completed or the specified address range is left. New measurement data is stored into temporary registers and the PS_DATA registers will be updated as soon as there is no on-going I2C read operation to the address range 0x07 to 0x18.

0x08		PS_DATA_0 (default = 0x00)								
	B7	B7 B6 B5 B4 B3 B2 B1 B0								
		PS Data Low								



Optical Sensor LTR-578ALS-02

0x09		PS_DATA_1 (default = 0x00)								
	B7	B6	В5	B4	В3	B2	B1	В0		
		Rese	erved		Overflow		PS Data Higl	h		

Field	Address	Bits	Default	Description		
PS Data, Low	0x08	7:0	00000000		PS ADC lower byte data	
Reserved	0x09	7:4	000			
Quarflaur	0.400	2	0	0	Valid PS data (default)	
Overflow	0x09	3	0	1	Overflow of PS data	
PS Data,	0,400	2:0	000		PS ADC upper bute date	
High	0x09	2:0	000		PS ADC upper byte data	

ALS_DATA Register (0x0D / 0x0E / 0x0F) (Read Only)

The ALS Channel digital output data are expressed as a 16 to 20 bit unsigned integer data. When I2C read operation is active and points to any of the register address between 0x07 and 0x18, all 3 registers will be locked until the I2C read operation has been completed or the specified address range is left. This is to ensure that the data in the registers is from the same measurement even if an additional measurement cycle ends during the read operation. New measurement data is stored into temporary registers and the ALS_DATA registers will be updated as soon as there is no on-going I2C read operation to the address range 0x07 to 0x18.

0x0D		ALS_DATA _0 (default = 0x00)							
	B7	B7 B6 B5 B4 B3 B2 B1 B0							
		ALS DATA, Low							



Optical Sensor LTR-578ALS-02

0x0E		ALS DATA_ 1 (default = 0x00)							
	B7	B7 B6 B5 B4 B3 B2 B1 B0							
		ALS DATA, Middle							

0x0F		ALS_DATA_ 2 (default = 0x00)								
	B7	B7 B6 B5 B4 B3 B2 B1 B0								
		Rese	erved		ALS DATA, High					

Field	Address	Bits	Default	Description
ALS Data, Low	0x0D	7:0	00000000	ALS Data lower byte data
ALS Data, Middle	0x0E	7:0	00000000	ALS Data Middle byte data
		7:4	0000	Reserved
ALS Data, High	0x0F	3:0	0000	ALS Data Higher byte data

INT_CFG Register (0x19) (Read/Write)

This register controls the operation of the interrupt pin and functions. ALS and PS have independent interrupt signal and both ALS and PS interrupts are active low. PS interrupt is enabled by Bit 0, and it is threshold triggered based. Besides, ALS interrupt is enabled by Bit 2, and its output pin can be selected as either Normal Interrupt Mode or PS Logic Output Mode through Bit 1. Under Normal Interrupt Mode, the edge-triggered interrupt signal output will be maintains at active level until MAIN_STATUS register is read. While for PS Logic Output Mode, the interrupt pin output is updated after every measurement and output state is maintained between measurements.

0x19	INT_CFG (default = 0x10)											
	B7	B6	В5	B4	B3	B2	B1	В0				
	Reserved		ALS INT SELECT		Reserved	ALS INT PIN ENABLE	PS OUTPUT MODE	PS INT PIN ENABLE				



Optical Sensor LTR-578ALS-02

Field	Bits	Default	Descrip	tion		
Reserved	7:6	00				
ALS Interrupt	4:5	01	00	Reserved		
Select	4.5	01	01	ALS Channel(Default)		
Reserved	3	0	0	Must be 0		
ALS Interrupt	2	0	0	ALS interrupt disabled (default)		
Pin Enable	2	0	1	ALS interrupt enabled		
PS OUTPUT	1	0	0	Normal Interrupt Mode: After interrupt event, INT output pin maintains active level until MAIN_STATUS register is read (default)		
MODE	I		1	PS Logic Output Mode: INT output pin is updated after every measurement and maintains output state between measurements.		
PS Interrupt	0	0	0	PS interrupt enabled (default)		
Pin Enable	0	0	1	PS interrupt enabled		

INT_PST Register (0x1A) (Read/Write)

This register controls the N number of times the measurement data is outside the range defined by the upper and lower threshold limits before asserting the interrupt.

0x1A		INT_PST (default = 0x00)										
	B7	B7 B6 B5 B4 B3 B2 B1 B0										
		ALS P	ersist		PS Persist							

Field	Bits	Default		Description
			0000	Every ALS value out of threshold range asserts an interrupt (default)
ALS	ALS 7:4 0000	0000	0001	2 consecutive ALS values out of threshold range assert an interrupt
Persist				
			1111	16 consecutive ALS values out of threshold range assert an interrupt





Optical Sensor LTR-578ALS-02

			0000	Every PS value out of threshold range asserts an interrupt (default)
PS Persist	3:0	0000	0001	2 consecutive PS values out of threshold range assert an interrupt
			1111	16 consecutive PS values out of threshold range assert an
				interrupt

PS_THRES Register (0x1B / 0x1C / 0x1D / 0x1E) (Read/Write)

The PS_THRES_UP and PS_THRES_LOW registers determines the upper and lower limit of the interrupt threshold value respectively. Interrupt will be triggered if measurement data in PS_DATA registers is exceeding the upper and lower limits.

0x1B	PS_THRES_UP_0 (default = 0xFF)											
	B7	B7 B6 B5 B4 B3 B2 B1 B0										
		PS Upper Threshold, Low										

0x1C	PS_THRES_UP_1 (default = 0x07)											
	B7	B7 B6 B5 B4 B3 B2 B1 B0										
			Reserved	PS Up	per Threshol	d, High						

0x1D		PS_THRES_LOW_0 (default = 0x00)										
	B7	B7 B6 B5 B4 B3 B2 B1 B0										
		PS Lower Threshold, Low										

0x1E	PS_THRES_LOW_1 (default = 0x00)										
	B7	B7 B6 B5 B4 B3 B2 B1 B0									
			Reserved	PS Lov	wer Threshol	d, High					



Optical Sensor LTR-578ALS-02

Field	Address	Bits	Default	Description
PS Upper Threshold, Low	0x1B	7:0	11111111	PS Upper Interrupt Threshold, Low byte
Reserved	0x1C	7:3	00000	
PS Upper Threshold, High	0x1C	2:0	111	PS Upper Interrupt Threshold, High byte
PS Lower Threshold, Low	0x1D	7:0	00000000	PS Lower Interrupt Threshold, Low byte
Reserved	0x1E	7:3	00000	
PS Lower Threshold, High	0x1E	2:0	000	PS Lower Interrupt Threshold, High byte

PS_CAN Register (0x1F / 0x20) (Read/Write)

This register defines the offset compensation value for proximity offsets caused by device variations, optical crosstalk and other environment factors. This register sets the PS cancellation value to be subtracted from the measured PS data before the data is transferred to the PS_DATA registers.

0x1F	PS_CAN_0 (default = 0x00)										
	B7	B7 B6 B5 B4 B3 B2 B1 B0									
		PS Cancellation Level, Low									

0x20	PS_CAN_1 (default = 0x00)										
	B7	B7 B6 B5 B4 B3 B2 B1 B0									
		Reserved PS Cancellation Level, High									

Field	Address	Bits	Default	Description
PS Cancellation Level, Low	0x1F	7:0	0000000	PS Cancellation Level, Low byte
Reserved	0x20	7:3	00000	
PS Cancellation Level, High	0x20	2:0	000	PS Cancellation Level, High byte

23/40



Data Sheet Optical Sensor LTR-578ALS-02

ALS_THRES Register (0x21 / 0x22 / 0x23 / 0x24 / 0x25 / 0x26) (Read/Write)

The ALS_THRES_UP (up to 20-bits) and ALS_THRES_LOW (up to 20-bits) registers determines the upper and lower limit of the interrupt threshold value respectively. Interrupt will be triggered if measurement data in ALS_DATA is exceeding the upper and lower limits.

0x21	ALS_THRES_UP_0 (default = 0xFF)							
	B7 B6 B5 B4 B3 B2 B1 B0							
	ALS Upper Threshold, Low							

0x22		ALS_THRES_UP_1 (default = 0xFF)							
	B7	B6	B5	B4	B3	B2	B1	В0	
	ALS Upper Threshold, Mid								

0x23	ALS_THRES_UP_2 (default = 0x0F)								
	B7	B7 B6 B5 B4 B3 B2 B1 B0							
		Res	erved			ALS Upper TI	hreshold, Hig	gh	

0x24	ALS_THRES_LOW_0 (default = 0x00)								
	B7	B7 B6 B5 B4 B3 B2 B1 B0							
	ALS Lower Threshold, Low								

0x25	ALS_THRES_LOW_1 (default = 0x00)							
	B7	B6	B5	B4	B3	B2	B1	B0
	ALS Lower Threshold, Mid							

0x26	ALS_THRES_LOW_2 (default = 0x00)								
	B7	B7 B6 B5 B4 B3 B2 B1 B0							
		Reso	erved			ALS Lower TI	hreshold, Hig	gh	



Optical Sensor LTR-578ALS-02

Field	Address	Bits	Default	Description
ALS Upper	004	7:0	11111111	ALC upper interrupt threshold I out bute
Threshold, Low	0x21	7.0	1111111	ALS upper interrupt threshold, Low byte
ALS Upper	000	7.0		
Threshold, Mid	0x22	7:0	11111111	ALS upper interrupt threshold, Mid byte
ALS Upper	0	7:4	0000	Reserved
Threshold, High	0x23	3:0	1111	ALS upper interrupt threshold, High byte
ALS Lower	0	7:0	00000000	ALC lower interrupt threshold Low bute
Threshold, Low	0x24	7.0	00000000	ALS lower interrupt threshold, Low byte
ALS Lower	0x25	7:0	00000000	ALS lower interrupt threshold, Mid byte
Threshold, Mid	0x25	7.0	0000000	ALS lower interrupt timeshold, wild byte
ALS Lower	0x26	7:4	0000	Reserved
Threshold, High	0x20	3:0	0000	ALS lower interrupt threshold, High byte





Optical Sensor LTR-578ALS-02

10. Application Information

10.1 Lux Formula

Lux_Calc is the calculated lux reading and ALS DATA is the digital representation (output ADC) of ambient light level stored in the registers (Address: 0x0D-0x0F) regardless of light sources.

For no window (Clear window)

$$Lux_{Calc} = \frac{0.8 \times ALS_{DATA}}{(GAIN \times INT)}$$

For device under window (eg: Tinted window)

Window Factor is needed when device under Window glass with coated tinted ink. This is to compensate the light loss due to the lower transmission rate of the window glass.

$$Lux_{Calc} = \frac{0.8 \times ALS_{DATA}}{(GAIN \times INT)} \times Window Factor$$

Where:

ALS Gain	GAIN
X1	1
X3	3
X6	6
X9	9
X18	18

Resolution (bit) / Integration Time (ms)	INT
16-bit, 25ms	0.25
17-bit, 50ms	0.5
18-bit, 100ms	1
19-bit, 200ms	2
20-bit, 400ms	4



Optical Sensor LTR-578ALS-02

10.2 Device Operation (State Machine and Interrupt Features)

State Machine

Below diagram is the main state machine of LTR-578ALS.



During the ALS and PS Operation, ALS measurements can be activated by setting the ALS_Enable bit to 1, and PS measurement can be activated by setting the PS_Enable bit to 1. As soon as the PS and/or the ALS sensors become activated through an I2C command, the internal support blocks are powered on. Once the voltages and currents are settled (typically after 5ms), the state machine checks for trigger events from a measurement scheduler to start ALS or PS conversions according to the selected measurement repeat rates. Once PS_Enable or ALS_Enable is changed back to 0, a running conversion on the respective channel will be completed and the relevant ADCs and support blocks will move to power-down state.





Data Sheet Optical Sensor LTR-578ALS-02

Interrupt Features

This device generates independent ALS and PS interrupt signals that can be multiplexed and output to the INT output pin. The interrupt conditions are always evaluated after completion of a new conversion of the ALS and PS channels. The PS Logic Mode has priority over any other interrupt signal. If selected (PS Logic Mode = 1), no ALS interrupt can be signaled at the INT pad. ALS and PS interrupts as well as PS Logic Mode are active low at the INT pin.



ALS Interrupt

The ALS interrupt is enabled by Bit 2 (ALS INT Pin Enabled) of INT_CFG register (0x19). The ALS interrupt source is ALS channel. The INT is set when the data of the selected interrupt source is above the upper or below the lower threshold for a specified number of consecutive measurements set in ALS Persist in INT_PST register (0x1A). The Interrupt signal is also stored in MAIN_STATUS register (0x07) as flag bit in Bit 4 (ALS INT Status). This status flag bit is cleared by reading the MAIN_STATUS register. A cleared flag will also clear the interrupt signal on the INT pin.





Data Sheet Optical Sensor LTR-578ALS-02

PS Interrupt

The PS interrupt is enabled by Bit 0 (PS Interrupt Pin Enable). It triggers when the PS conversion result is above the upper or below PS threshold for a specified number of consecutive measurements set in PS Persist in INT_PST register (0x1A). The PS Logic Signal, Bit 2 of MAIN_STATUS register (0x07), is set to 0 when the PS data is below the lower PS threshold and it set to 1 if the PS data is above the upper PS threshold.

There are two options to indicate a PS interrupt signal on the INT pin: as a continuous logic signal or as an edge-triggered interrupt signal, which is cleared with the next read-out of the MAIN-STATUS register. The PS interrupt signal is also stored in MAIN_STATUS register (0x07) as flag bit in Bit 1 (PS INT Status). This status flag bit is cleared by reading the MAIN_STATUS register. The PS interrupt behavior is as shown below.



29/40



Optical Sensor LTR-578ALS-02

11. Pseudo Codes Examples

Slave a	Iddress
---------	---------

Slave_Addr = 0xA6

MAIN_CTRL Register

// This defines the operating modes of the ALS // Default settings is 0x00 (ALS standby, PS standby)

Register_Addr = 0x00Command = 0x03

// MAIN_CTRL register //

ALS/PS in Active Mode,

WriteByte(Slave_Addr, Register_Addr, Command);

PS_LED Register

// This defines the LED pulse modulation frequency and Peak current. // Default setting is 0x36 (Pulse Freq = 60kHz, peak current = 100mA).

Register_Addr = 0x01	// PS_LED register	
Command = 0x36	//	Pulse Freq = 60kHz, Peak Current =100mA
	// Command = 0x46	Pulse Freq = 70kHz, Peak Current =100mA
	// Command = 0x44	Pulse Freq = 70kHz, Peak Current = 50mA
	// Command = 0x76	Pulse Freq = 100kHz, Peak Current = 100mA
	// Command = 0x77	Pulse Freq = 100kHz, Peak Current = 125mA
WriteByte(Slave Addr Register Addr C	(ommand)	

WriteByte(Slave_Addr, Register_Addr, Command)

PS_PULSES Register

// This controls the number of PS LED pulses emitted. // Default setting of the register is 0x08 (8 Pulses)

Register_Addr = 0x02	// PS_PULSES register	
Command = 0x08	//	8 pulses
	// Command = 0x00	0 (no light)
	// Command = 0x04	4 pulses
	// Command = 0x20	32 pulses
WriteBute(Slave Addr Register Addr Comm	(hand	

WriteByte(Slave_Addr, Register_Addr, Command)

PS_MEAS_RATE Register

//This controls the PS Resolution and measurement rate. // Default setting of the register is 0x45 (PS Resolution = 8 bit, Measurement Rate = 100ms)

Register_Addr = 0x03 Command = 0x45

// PS_MEAS_RATE regis	ster
//	Resolution = 8 bit, Meas Rate = 100ms
// Command = 0x47	Resolution = 8 bit Meas Rate = 400ms
// Command = 0x5D	Resolution = 11 bit Meas Rate = 100ms
n -	

WriteByte(Slave_Addr, Register_Addr, Command)

30/40



Optical Sensor LTR-578ALS-02

ALS_MEAS_RATE Register

// This controls the ALS measurement resolution and measurement rate.

// Default setting of the register is 0x22 (Resolution = 18 Bit, Measurement rate of 100ms)

Register_Addr = 0x04	// ALS_MEAS_RATE reg	gister
Command = 0x41	//	Resolution = 16 bit, Meas Rate =50ms
	// Command =0x25	Resolution = 18 bit, Meas Rate =1000ms
	// Command =0x02	Resolution = 20 bit, Meas Rate =100ms
WriteByte(Slave_Addr, Register_Addr, Comm	nand)	

syle(Slave_Addi, Register_Addi, Co and)

ALS _GAIN Register

// This controls the ALS Gain Range. // Default setting of the register is 0x01 (Gain Range = 3)

Register_Addr = 0x05	// ALS_GAIN register	
Command = 0x00	//	Gain = 1
	// Command =0x04	Gain = 18
WriteByte(Slave_Addr, Register_Addr, Comm	hand)	

MAIN_STATUS Register (Read Only)

// This Register contains the information on Interrupt, ALS and PS data status.

Register_Addr = 0x07 Data = ReadByte(Slave_Addr, Register_Addr)	// MAIN_STATUS register address)
Power_ON_Status = Data & 0x20	// If 0x20 Part went through power-up event // If 0x00 Normal
ALS_Interrupt_Status = Data & 0x10	<pre>// If 0x10 Interrupt triggered // If 0x00 Interrupt condition not fulfilled</pre>
ALS_Data_Status = Data & 0x08	// If 0x08 ALS data is new // If 0x00 Old (previously read) Data
PS_Logic_Signal_Status = Data & 0x04	// If 0x04 Object is near // If 0x00 Object is far
PS_Interrupt_Status = Data & 0x02	<pre>// If 0x02 Interrupt triggered // If 0x00 Interrupt condition not fulfilled</pre>
PS_Data_Status = Data & 0x01	// If 0x01 PS data is new // If 0x00 Old (previously read) Data
PS_DATA Registers (Read Only)	

//The register 0x08 contains PS ADC lower byte data. //The register 0x09 contains PS ADC 3 bits of upper byte data and PS Overflow flag //These registers should be read as a group, with the lower address being read first.

Register_Addr = 0x08	// PS_DATA0 low byte address
Data0=ReadByte(Slave_Addr, R	egister_Addr) // Data= PS ADC lower byte data

Register_Addr = 0x09	// PS_DATA1 high byte address
Data=ReadByte(Slave_Addr, Register_Addr)	// Data= PS ADC high byte data
Data1=Data&0x03	// Mask with 0x03 to extract data

PS_ADC_Data = (Data1 << 8) | Data0 Overflow_status = Data & 0x08

// Shift and combine lower and upper bytes to give 11-bit PS data // If 0x08 PS Data is overflow // If 0x00 PS Data is valid

31/40

Part No. : LTR-578ALS-02 BNS-OD-FC002/A4



Optical Sensor LTR-578ALS-02

CLEAR_DATA Registers (Read Only)

//The register 0x0A contains CLEAR_DATA ADC 0 lower byte data.
 //The register 0x0B contains CLEAR_DATA ADC 1 middle byte data.
 //The register 0x0C contains CLEAR_DATA ADC 2 upper byte data.
 //These registers should be read as a group, with the lower address being read first.

 Register_Addr = 0x0A
 // CLEAR_DATA_0 low byte address

 Data0=ReadByte(Slave_Addr, Register_Addr)

 Register_Addr = 0x0B
 // CLEAR_DATA_1 middle byte address

 Data1=ReadByte(Slave_Addr, Register_Addr)

 Register_Addr = 0x0C
 // CLEAR_DATA_2 upper byte address

 Data2=ReadByte(Slave_Addr, Register_Addr)

 CLEAR_Data =(Data2<<16)| (Data1 << 8) | Data0</td>

 // Shift and combine all register data to get CLEAR ADC Data

ALS_DATA Registers (Read Only)

// The register 0x0D contains ALS ADC lower byte data. // The register 0x0E contains ALS ADC 1 middle byte data. // The register 0x0F contains ALS ADC 2 upper byte data. // These registers should be read as a group, with the lower address being read first. Register_Addr = 0x0D // ALS_DATA_0 low byte address Data0=ReadByte(Slave_Addr, Register_Addr) Register_Addr = 0x0E // ALS_DATA_1 middle byte address Data1=ReadByte(Slave_Addr, Register_Addr) Register_Addr = 0x0F // ALS_DATA_2 upper byte address Data2=ReadByte(Slave_Addr, Register_Addr) ALS ADC_Data = (Data2<<16)| (Data1 << 8) | Data0</pre>

// Shift and combine all register data to get ALS ADC Data

ALS_DATA_COMP Registers (Read Only)

// The register 0x16 contains ALS_COMP ADC lower byte data. // The register 0x17 contains ALS_COMP ADC 1 middle byte data. // The register 0x18 contains ALS_COMP ADC 2 upper byte data. // These registers should be read as a group, with the lower address being read first. Register_Addr = 0x16 // ALS_DATA_COMP_0 low byte address Data0=ReadByte(Slave_Addr, Register_Addr) Register_Addr = 0x17 // ALS_DATA_COMP_1 middle byte address Data1=ReadByte(Slave_Addr, Register_Addr) Register_Addr = 0x18 // ALS_DATA_COMP_2 upper byte address

Data2=ReadByte(Slave_Addr, Register_Addr)

ALS_COMP_ADC_Data =(Data2<<16)| (Data1 << 8) | Data0

// Shift and combine all register data to get ALS_COMP ADC Data

32/40



Optical Sensor LTR-578ALS-02

INT_CFG Register

//This register controls the operation of the interrupt pins and options to trigger interrupt for ALS and PS. //The default value for this INT_CFG register is 0x10 (Interrupts inactive for both ALS and PS)

Register_Addr = 0x19 Command = 0x15	<pre>// INT_CFG Register add // Interrupt CH = ALS, AL</pre>	Iress S Interrupt Enable, Normal trigger mode; PS Interrupt Enable
	// Command = 0x17	Interrupt source CH = ALS, ALS Interrupt Enable,
	//	PS Logic Output Mode; PS Interrupt Enable
	// Command = 0x05	Interrupt source CH = CLEAR, ALS Interrupt Enable,
	//	Normal Trigger Mode; PS Interrupt Enable
	// Command = 0x14	Interrupt CH = ALS, ALS Interrupt Enable,
	//	Normal Trigger Mode; PS Interrupt Disable
	// Command = 0x11	Interrupt CH = ALS, ALS Interrupt Disable,
	//	Normal Trigger Mode; PS Interrupt Enable

WriteByte(Slave_Addr, Register_Addr, Command)

INTERRUPT_PERSIST Register

// This register sets the ALS and PS persist level. // The default setting is 0x00. Interrupt at every ALS and PS reading outside set thresholds.

Register_Addr = 0x1A// INT_PST register // Interrupt for every ALS and PS value outside threshold Command = 0x00// Command =0x10 Subsequent 2 ALS and every PS value, outside threshold range Subsequent 2 ALS and 2 PS values, outside threshold range // Command =0x11 // Command =0x35 Subsequent 4 ALS and subsequent 6 PS values, outside threshold range

WriteByte(Slave_Addr, Register_Addr, Command)

PS_THRES Registers

// The register 0x1B contains PS Interrupt upper threshold lower byte data (PS_THRES_UP_0) // The register 0x1C contains PS Interrupt upper threshold upper byte data (PS_THRES_UP_1) // The register 0x1D contains PS Interrupt lower threshold lower byte data (PS_THRES_LOW_0) // The register 0x1E contains PS Interrupt lower threshold upper byte data (PS_THREH_LOW_1)

// To set PS Upper threshold for Interrupt Upper_Threshold_Value=1000 Data1 = Upper_Threshold_Value >> 8 Data0 = Upper_Threshold_Value & 0xFF Register_Addr = 0x1BWriteByte(Slave_Addr, Register_Addr, Data0) Register_Addr = 0x1CWriteByte(Slave_Addr, Register_Addr, Data1)

// To set PS Lower threshold for Interrupt Lower_Threshold_Value=100 Data1 = Lower_Threshold_Value >> 8 Data0 =Lower_Threshold_Value & 0xFF Register_Addr = 0x1D WriteByte(Slave Addr, Register Addr, Data0) Register_Addr = 0x1E WriteByte(Slave_Addr, Register_Addr, Data1) // Example 1000 // Shift right to extract the upper byte // Mask to extract lower byte. // PS_THRES_UP_0 Register address // PS_THRES_UP_1 Register address

// Example 100 // Shift right to extract the upper byte // Mask to extract lower byte.

// PS_THRES_LOW_0 Register address

// PS_THRES_LOW_1 Register address

33/4(

Part No. : LTR-578ALS-02 BNS-OD-FC002/A4



Optical Sensor LTR-578ALS-02

PS_CAN Registers

//The register 0x1F contains PS cancellation lower byte data (PS_CAN_0)
//The register 0x20 contains 3 bits of PS cancellation upper byte data (PS_CAN_1)

ALS_THRES Registers

//The register 0x21 contains ALS Interrupt upper threshold lower byte data (ALS_THRES_UP_0) //The register 0x22 contains ALS Interrupt upper threshold 1 upper byte data (ALS_THRES_UP_1) //The register 0x23 contains ALS Interrupt upper threshold 2 upper byte data (ALS_THRES_UP_2)

//The register 0x24 contains ALS Interrupt lower threshold lower byte data (ALS_THRES_LOW_0) //The register 0x25 contains ALS Interrupt lower threshold 1 upper byte data (ALS_THRES_LOW_1) //The register 0x26 contains ALS Interrupt lower threshold 2 upper byte data (ALS_THRES_LOW_2)

// To set ALS Upper threshold for Interrupt Upper_Threshold_Value=1000 // Example 1000 Data2 = Upper_Threshold_Value >> 16 // Shift right to extract the 2 upper byte Data1 = Upper_Threshold_Value >> 8 // Shift right to extract the 1 upper byte Data0 = Upper_Threshold_Value & 0xFF // Mask to extract lower byte. Register_Addr = 0x21 // ALS_THRES_UP_0 Register address WriteByte(Slave_Addr, Register_Addr, Data0) Register_Addr = 0x22// ALS_THRES_UP_1 Register address WriteByte(Slave_Addr, Register_Addr, Data1) Register Addr = 0x23// ALS_THRES_UP_2 Register address WriteByte(Slave_Addr, Register_Addr, Data2) // To set ALS Lower threshold for Interrupt Lower_Threshold_Value=100 // Example 100 Data2 = Lower_Threshold_Value >> 16 // Shift right to extract the 2 upper byte Data1 = Lower_Threshold_Value >> 8 // Shift right to extract the 1 upper byte Data0 = Lower_Threshold_Value & 0xFF // Mask to extract lower byte. Register Addr = 0x24// ALS_THRES_LOW_0 Register address WriteByte(Slave_Addr, Register_Addr, Data0) Register_Addr = 0x25// ALS_THRES_LOW_1 Register address WriteByte(Slave_Addr, Register_Addr, Data1) Register_Addr = 0x26// ALS_THRES_LOW_2 Register address WriteByte(Slave_Addr, Register_Addr, Data2)

34/4(

Part No. : LTR-578ALS-02 BNS-OD-FC002/A4



Optical Sensor LTR-578ALS-02

12. Recommended Leadfree Reflow Profile



Process Zone	Symbol	ΔΤ	Maximum ∆T/∆time or Duration
Heat Up	P1, R1	25°C to 150°C	3°C/s
Solder Paste Dry P2, R2 150°C to		150°C to 200°C	100s to 180s
Solder Reflow	P3, R3	200°C to 260°C	3°C/s
	P3, R4	260°C to 200°C	-6°C/s
Cool Down	P4, R5	200°C to 25°C	-6°C/s
Time maintained above liquid	us point , 217°C	> 217°C	60s to 90s
Peak Temperature		260°C	-
Time within 5°C of actual Peak Temperature		> 255°C	20s
Time 25°C to Peak Temperature		25°C to 260°C	8mins

It is recommended to perform reflow soldering no more than twice.

35/40



Optical Sensor LTR-578ALS-02

13. Moisture Proof Packaging

All LTR-578ALS-02 are shipped in moisture proof package. Once opened, moisture absorption begins. This part is compliant to JEDEC J-STD-033A Level 3.

Time from Unsealing to Soldering

After removal from the moisture barrier bag, the parts should be stored at the recommended storage conditions and soldered within seven days. When the moisture barrier bag is opened and the parts are exposed to the recommended storage conditions for more than seven days, the parts must be baked before reflow to prevent damage to the parts.

Recommended Storage Conditions

Storage Temperature	10°C to 30°C
Relative Humidity	Below 60% RH

Baking Conditions

Package	Temperature	Time
In Reels	60°C	48 hours
In Bulk	100°C	4 hours

Baking should only be done once.





Optical Sensor LTR-578ALS-02

14. Recommended Land Pattern and Metal Stencil Aperture



Recommended Land Pattern



Note: All dimensions are in millimeters



Part No. : LTR-578ALS-02 BNS-OD-FC002/A4



Data Sheet Optical Sensor LTR-578ALS-02

Recommended Metal Stencil Aperture

It is recommended that the metal stencil used for solder paste printing has a thickness (t) of 0.11mm (0.004 inches / 4 mils) or 0.127mm (0.005 inches / 5 mils).

The stencil aperture opening is recommended to be 0.75mm x 0.75mm which has the same dimension as the land pattern. This is to ensure adequate printed solder paste volume and yet no shorting.







Optical Sensor LTR-578ALS-02

15. Package Dimension for Tape and Reel



Notes:

- 1. All dimensions are in millimeters
- 2. Empty component pockets sealed with top cover tape
- 3. 13 inch reel 8000 pieces per reel
- 4. In accordance with ANSI/EIA 481-1-A-1994 specifications

39/40

Part No. : LTR-578ALS-02 BNS-OD-FC002/A4



Optical Sensor LTR-578ALS-02

Revision Table:

Version	Update	Page	Date
1.0	Datasheet as created	Total 40	10-Aug-2016

