Product/Process Change Notifications



PCN - 16 082

2016

Release Date: September 15

| | | | | Release Date: September 15 2016 | |
|---|--|----|------|---------------------------------|--|
| Product Name: | ExaMAX | | | | |
| | 3 pair right angle receptacle and right angle header | | | | |
| Product Manager: | David Jiang | | | | |
| Subject: | Notification of Planned Change | | | | |
| Distribution: | Global | | | | |
| Type of Change: | Design Change | | | | |
| Change Description: Reason for Change: | Adding a location hole on ground plate. This change will not impact product performance and application.(attached picture) Automation feature Fore Change Process Improvement. Automation assembly process requires locating hole on ground shield plate. | | | | |
| Affected Parts: | refer to attachment | | | | |
| Effective Date of Change: | October 30, 2016 | | | | |
| Last Time Buy Date: | NA | | | 4 | |
| Last Disty Return Date: | NA | | | 1 | |
| Last Time Shipment Date | NA | | | | |
| Datasheet Attached? | No | | | 1 | |
| Qual/Test Data Attached? | No | | | | |
| Samples Availability Date: | September | 01 | 2016 | | |
| Available Alternatives? | Select | | | | |
| Questions? | Contact your local AFCI Representative, or Product Manager | | | | |
| | David Jiang/Product Manager | | | | |
| | 0012242486736 David.Jiang@FCI.com | | | | |
| | | | | | |

Note:

Customers should contact Product Manager (or their local AFCI Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .