

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following part numbers are now obsolete with immediate effect.

- M40-620xx46
- NOTE: M40-620xx46R are not affected, and are still available these are identical connectors, but packaged in tape & reel

Please see the following spreadsheet for a detailed list of affected items: <u>https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_2023-02-</u> <u>21.xlsx</u>

Unfortunately, we are no longer able to support this packing variation on these product ranges. Alternative items are available; please see the attached list for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M40-6000946	M40-600_obsolete.pdf	Immediate	M40-6000946R	M40-600R.pdf
M40-6001546	M40-600_obsolete.pdf	Immediate	M40-6001546R	M40-600R.pdf
M40-6002146	M40-600_obsolete.pdf	Immediate	M40-6002146R	M40-600R.pdf
M40-6002546	M40-600_obsolete.pdf	Immediate	M40-6002546R	M40-600R.pdf
M40-6003146	M40-600_obsolete.pdf	Immediate	M40-6003146R	M40-600R.pdf
M40-6004146	M40-600_obsolete.pdf	Immediate	M40-6004146R	M40-600R.pdf
M40-6005146	M40-600_obsolete.pdf	Immediate	M40-6005146R	M40-600R.pdf