BOURNS®

Product Change Notification

INDUCTIVE COMPONENTS



August 9, 2018

Bourns® Part Number SRP1250-6R0MA and SRP1270-2R2M Shielded Power Inductors

Change to Removal Process of the Magnetic Wire Insulation

Effective immediately, Bourns is changing the removal process of the magnetic wire insulation in part numbers SRP1250-6R0MA and <u>SRP1270-2R2M</u> from a semi-automated machine to an automated laser machine. Utilizing a laser technology helps enable a thorough removal of the wire coating.

The manufacturing process change will not affect the inductor's form, fit or function. The quality and reliability of the inductor should be improved.

Affected Part Numbers
SRP1250-6R0MA
SRP1270-2R2M

If you have any questions or need additional information, please feel free to contact Customer Service/Inside Sales.

IC1847

 Americas:
 Tel: +1-951 781-5500
 EMEA:
 Tel: +36 88 520 390
 Asia-Pacific:
 Tel: +886-2 2562-4117

 americus@bourns.com
 eurocus@bourns.com
 asiacus@bourns.com