ArtNumber: 701720	~
	of the devices for the mass production definitely
Subles can deviate in the secution from the sec	Dimensions and tolerances can be specified only after the testing of
' All dimensions in mm.	·
All framed values will be used for dimension checking ! The Products of Renata SA are neither designed nor authorized for use in certain areas of application of environment.	
For further details we refer to our webpage www.renata.com/downloads/restriction_of_use Rev. ① 01.11.14 PWu Rev. ○ Image: Customer Rev. ② 26.08.19 PWu Rev. ○ Image: Customer Customer Rev. ② 26.08.19 PWu Rev. ○ Image: Customer Oate Rev. ○ Rev. ○ Image: Customer Oate Image: Customer Title: Customer Scale Drawn Checked Approver Approver Approver	24.11.06 SRi
renata CH-4452 Itingen 3.916	4.4-2