1 Products affected

Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.
SBU PG PUG Type				
02 005 016 0000001210	See list below	Connectors	6762 (screw-on)	
*SBU (2-digit) / PG (3-digit) / PUG (3-digit)) / Type (10-digit)		· · · · · ·	

List of part numbe	rs affected			
3-100-970	4304.4104	4304.6055	4304.6061	4304.6162
4304.4100	4304.6049	4304.6057	4304.6070	4304.6224
4304.4101	4304.6052	4304.6058	4304.6071	
4304.4102	4304.6053	4304.6059	4304.6152	
4304.4103	4304.6054	4304.6060	4304.6157	

2 Type of change

- 1. Change of approval markings from UR and CSA to the combined cURus on the product socket according to standard update of UL/CSA 60320-1
- 2. Backside of flange with ribs and less material

3 Detailed description of change



4 Reason of change

- 1. The change is due to a standard update to UL/CSA 60320-1
- 2. To improve the moulding process and to avoid flow lines

5 Release date

The change takes effect in ww 19/2020 (Date code 2019 or higher on label) and last approx. 6 months depending on the variant and stock. This change has no effect on the validity of the approval certificates

Product Change Notification				PCN 6762 (screw-on)				
owner	creation date	release date	released by	change order no	rev	page	D10-043-840	
huberth	19.03.2020	26.03.2020	muehlema	2019628	А	1 of 2		

6 Impact of change and recommended action

Form	Yes	1. Socket new with cURus approval marking			
Form	Yes	2. Less material and new a rib construction on the backside of flange			
Fit	No	No change for dimension			
Function	No	No change in function			
Manufacturing	No	No change for manufacturing site			
Label	No	No change on label			
Packaging	No	No change in packaging			

7 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet 6762	

Product Change Notification			PCN 6762 (screw-on)					
owner	creation date	release date	released by	change order no	rev	page	D10 042 040	
huberth	19.03.2020	26.03.2020	muehlema	2019628	А	2 of 2	D10-043-840	