

PRODUCT DISCONTINUANCE NOTICE# CQ-14-03

ISSUE DATE: April 25, 2014

LAST BUY DATE: April 25, 2015

LAST SHIP DATE: July 25, 2015

REASON FOR DISCONTINUANCE:

The sales activity has declined to a level that warrants the discontinuance of these products. Some of these devices may have an alternate standard device or a suggested functional replacement.

Attached is a list of affected parts with any potential drop in replacement parts or suggested functional replacement parts.

Customers should contact IDT within 90 days of receipt of this notification if they have any additional questions or concerns related to this Product Discontinuance Notice. You may contact your local IDT Sales office listed on our web site at <u>www.IDT.com</u> or the marketing contact listed below:

NET

clocks@idt.com

Final orders may be submitted at any time prior to the last buy date indicated above. All orders shall be subject to acceptance per IDT standard terms and conditions.



| Device to be Discontinued | Drop in Replacement | Functional Replacement | Replacement Part Availability | Product Group | Remark |
|---------------------------|---------------------|---|-------------------------------|---------------|--------|
| 810525AGILF | None | None | N/A | NET | |
| 810525AGILFT | None | None | N/A | NET | |
| 813253BGLF | None | 813N252CKI-02LF, 813N252BKI-04LF | Available Now | NET | |
| 813253BGLFT | None | 813N252CKI-02LFT, 813N252BKI-04LFT | Available Now | NET | |
| 813L2500BGLF | None | 813N252CKI-02LF, 813N252BKI-04LF | Available Now | NET | |
| 813L2500BGLFT | None | 813N252CKI-02LFT, 813N252BKI-04LFT | Available Now | NET | |
| 8344AY-01LF | None | 8344BYLF | Available Now | NET | |
| 8344AY-01LFT | None | 8344BYLFT | Available Now | NET | |
| 8431EM-11LF | None | 8431AMI-21LF | Available Now | NET | |
| 8431EM-11LFT | None | 8431AMI-21LFT | Available Now | NET | |
| 8501BYLF | None | None | N/A | NET | |
| 8501BYLFT | None | None | N/A | NET | |
| 8512062AGILF | None | 8512061AGILF, 851S201CKILF | Available Now | NET | |
| 8512062AGILFT | None | 8512061AGILFT, 851S201CKILFT | Available Now | NET | |
| 8633AF-01LF | None | 8735AY-31LF,8735BYI-01LF, 8735BKI-01LF | Available Now | NET | |
| 8633AF-01LFT | None | 8735AY-31LFT,8735BYI-01LFT, 8735BKI-01LFT | Available Now | NET | |
| 8634BK-01LF | None | 8735AY-31LF,8735BYI-01LF, 8735BKI-01LF | Available Now | NET | |
| 8634BK-01LFT | None | 8735AY-31LFT,8735BYI-01LFT, 8735BKI-01LFT | Available Now | NET | |
| 8634BY-01LF | None | 8735AY-31LF,8735BYI-01LF, 8735BKI-01LF | Available Now | NET | |
| 8634BY-01LFT | None | 8735AY-31LFT,8735BYI-01LFT, 8735BKI-01LFT | Available Now | NET | |
| 8701AY-01LF | None | 8701CYLF | Available Now | NET | |
| 8701AY-01LFT | None | 8701CYLFT | Available Now | NET | |
| 8725AYI-01LF | 8725BY-01LF | None | Available Now | NET | |
| 8725AYI-01LFT | 8725BY-01LFT | None | Available Now | NET | |