Light is OSRAM



15 June 2021

Not For New Design **OS-NFND-2021-016**

 Expected discontinuation date:
 01.09.2021

 Reason:
 The following products have reached their end of life.

 OSRAM OS Expectations:
 Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions. Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products. Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.



Please direct your feedback to your local Sales office.



Not for new design products				Recommended Replacement		
Device	Ordering Code	Brand	Expected PDN start	Device	Datasheet Ordering Code	Brand
GF QSSPA1.24-1T3T-1-1-350-R18	Q65113A0105	OSCONIQ	01.09.2021	GF CSSPM1.24-2T4T-1-1-350-R33	Q65113A1081	OSLON

