- TE	Product Change Notification		
	Internal Registra	tion Date	2022-07-15 YYYY.MM.DD
	TE Connectivity		
PCN number 20220715	PCN Dat	e	2022-07-15 YYYY.MM.DD
TE would like to inform you that some of obsolescence status. As a courtesy to yo In case of any further questions about th Connectivity Sales Engineer. Affected pa	u, we are offering a last time b is change, please contact your	uy period FE	
General Product Description			
This PCN may cover multiple products. Please refer to the	he body of this email for details on part nu	nbers.	
Description of Changes The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000	100; 832M1-0200; 832M1-0		
The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000	100; 832M1-0200; 832M1-0 0006-500PG		
The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000 Reason for Changes Please see Last Order Date and Last Ship Date below to	100; 832M1-0200; 832M1-0 0006-500PG		
The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000 Reason for Changes	100; 832M1-0200; 832M1-0 0006-500PG		
The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000 Reason for Changes Please see Last Order Date and Last Ship Date below to	100; 832M1-0200; 832M1-0 0006-500PG place your last time buys accordingly.		
The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000 Reason for Changes Please see Last Order Date and Last Ship Date below to Estimated Dates: Last Order Date (Obsolete parts Only): 2022-10-15 Last Ship Date (Obsolete parts Only)	100; 832M1-0200; 832M1-0 0006-500PG place your last time buys accordingly.	500; 834 /A	M1-2000;
The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000 Reason for Changes Please see Last Order Date and Last Ship Date below to Estimated Dates: Last Order Date (Obsolete parts Only): 2022-10-15	100; 832M1-0200; 832M1-0 0006-500PG place your last time buys accordingly.	500; 834 /A	M1-2000;
The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000 Reason for Changes Please see Last Order Date and Last Ship Date below to Estimated Dates: Last Order Date (Obsolete parts Only): 2022-10-15 Last Ship Date (Obsolete parts Only) 2023-02-31 *Shipments cannot be scheduled exceeding 1 year from	100; 832M1-0200; 832M1-0 0006-500PG place your last time buys accordingly.	500; 834 //A I Parts Only)	M1-2000;
The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000 Reason for Changes Please see Last Order Date and Last Ship Date below to Estimated Dates: Last Order Date (Obsolete parts Only): 2022-10-15 Last Ship Date (Obsolete parts Only) 2023-02-31 *Shipments cannot be scheduled exceeding 1 year from PCN date	100; 832M1-0200; 832M1-0 0006-500PG place your last time buys accordingly.	500; 834 //A I Parts Only)	M1-2000;
The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000 Reason for Changes Please see Last Order Date and Last Ship Date below to Estimated Dates: Last Order Date (Obsolete parts Only): 2022-10-15 Last Ship Date (Obsolete parts Only) 2023-02-31 *Shipments cannot be scheduled exceeding 1 year from PCN date Part Number(s) being Modified: Refer to email	100; 832M1-0200; 832M1-0 0006-500PG place your last time buys accordingly.	500; 834	M1-2000;
The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000 Reason for Changes Please see Last Order Date and Last Ship Date below to Estimated Dates: Last Order Date (Obsolete parts Only): 2022-10-15 Last Ship Date (Obsolete parts Only) 2023-02-31 *Shipments cannot be scheduled exceeding 1 year from PCN date Part Number(s) being Modified: Refer to email	100; 832M1-0200; 832M1-0 0006-500PG  place your last time buys accordingly.  First Date To Ship (Changed Parts Only): Last Date for mixed Shipments: (Change	500; 834	M1-2000;
The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000 Reason for Changes Please see Last Order Date and Last Ship Date below to Estimated Dates: Last Order Date (Obsolete parts Only): 2022-10-15 Last Ship Date (Obsolete parts Only) 2023-02-31 *Shipments cannot be scheduled exceeding 1 year from PCN date Part Number(s) being Modified: Refer to email	100; 832M1-0200; 832M1-0 0006-500PG  place your last time buys accordingly.  First Date To Ship (Changed Parts Only): Last Date for mixed Shipments: (Change Last Date for mixed Shipments: (Change Product	500; 834	M1-2000;
The part numbers listed on this email are being made of options and any questions or concerns. 832M1-0025; 832M1-0050; 832M1-0 834M1-6000; 86-050A-U; M3051-000 Reason for Changes Please see Last Order Date and Last Ship Date below to Estimated Dates: Last Order Date (Obsolete parts Only): 2022-10-15 Last Ship Date (Obsolete parts Only) 2023-02-31 *Shipments cannot be scheduled exceeding 1 year from PCN date Part Number(s) being Modified: Refer to email	100; 832M1-0200; 832M1-0 0006-500PG  place your last time buys accordingly.  First Date To Ship (Changed Parts Only): Last Date for mixed Shipments: (Change Last Date for mixed Shipments: (Change Product Process I	500; 834	M1-2000;