

Expertise Applied | Answers Delivered 8755 W. Higgins Road Suite 500 Chicago, IL 60631 www.littelfuse.com

March 11, 2015

## LF PTN# A0070 Notification of Obsolescence of Strip Fuse series 157.5919.xxx1

Dear Valued Customer,

Littelfuse Inc. would like to notify you of the obsolescence of our Strip Fuse 60 T series. An essential component of this product is no longer available, so the obsolescence will take effect upon depletion of existing stock. There is no direct replacement for this variation of Strip Fuse.

Material to be Obsolete	Description		Replacement
157.5919.5401	FUSE STRIP 60 T WITH HO	USING 40A	No direct replacement
157.5919.5501	FUSE STRIP 60 T WITH HO	USING 50A	No direct replacement
157.5919.5631	FUSE STRIP 60 T WITH HO	USING 63A	No direct replacement
157.5919.5801	FUSE STRIP 60 T WITH HO	USING 80A	No direct replacement
157.5919.6101	FUSE STRIP 60 T WITH HO	USING 100	No direct replacement
157.5919.6131	FUSE STRIP 60 T WITH HO	USING 130	No direct replacement
157.5919.6141	FUSE STRIP 60 T WITH HO	USING 135	No direct replacement
157.5919.6151	FUSE STRIP 60 T WITH HO	USING 150	No direct replacement
157.5919.6161	FUSE STRIP 60 T WITH HO	USING 160	No direct replacement
157.5919.6171	FUSE STRIP 60 T WITH HO	USING 175	No direct replacement
157.5919.6201	FUSE STRIP 60 T WITH HO	USING 200	No direct replacement
157.5919.6231	FUSE STRIP 60 T WITH HO	USING 230	No direct replacement
157.5919.6251	FUSE STRIP 60 T WITH HO	USING 250	No direct replacement

Please contact your local Littelfuse representative if you have any additional questions. We will be pleased to answer any questions you may have.

Thank you for your continued support.

Best Regards,

Jenny Kiolbasa

Jenny Kiolbasa Littelfuse Automotive Business Unit jkiolbasa@littelfuse.com