

## **Global Change Notification (GCN)**

Product Family	MX150	10692736	
		GCN Number	
Series	33472-04xx & 33472-44xx	June 22, 2015	
		Date Issued	
Reason For Change	Product Component Change		
Change Description	This letter is to inform you of a product change to a single component associated with the MX150 2x2 Receptacle Connector. The impacted component is the Mat Seal. The reason for this change is in response to the growing desire to use ISO wire. As such, the terminal hole geometry within the Mat Seal has been optimized to accept 0.35mm <sup>2</sup> wire while continuing to support larger wire up to 14AWG. The color of the seal will be changing from Light Blue to Rust Red. In addition to the color change, part numbers will be changing from 33472-04xx to 33472-40xx and from 33472-44xx to 33472-41xx. A full list of replacement part numbers can be provided upon request. Part numbers 33472- 04xx and 33472-44xx will become obsolete after Implementation Date. PPAP's can be offered at the end of August 2015 should your company require a resubmission.		



October 31, 2015

Last Time Ship Date for Obsolete Parts

December 31, 2015

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com