

Product Family	Modular Jacks	10617422	
		GCN Number	
Series	85508, 95623	January 17, 2014	
		Date Issued	
Reason For Change	Product Component Change		
Change Description	The purpose of this letter is to inform you of a modification to the shield 95124- 0804 to faciliate mating with competitor plug on part 956232881. As this sheild is common to a number of other jack parts these are also effected. This mofication does not effect the function of the part, mechanically or electrically. So there is no risk to you the customer.		
Before Shield Flap 11.75mm	After Shield Flap 7.00mm		
Part Numbers Affected	Please refer to CustomerPartList.csv attache	ed to e-mail message.	
Reason For Short Notice Exception			
Assessment Of Change (How Product Will Be Qualified & Validated)	From the images below, there is a small section of the shield removed from where it folds around the opening in the Modular jack. This will have no effect on the function of the product.		
Internal Molex Qualification Date (Planned Date Information Available)	February 28, 2014		
Sample Availability Date (Changed Part)	January 17, 2014		
Date of Implementation	July 18, 2014		
Method of Identifying Change	On the initial shipments there will be a label shield	on the boxes stating modified	
Recommended Replacement Parts	N/A		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com