

December 11, 2020 Discontinued 9006 Series Product Family

Dear Valued Customer,

This letter serves as formal notification that Coto Technology has decided to discontinue the manufacturing of 9006 series product family, after a thorough review of our existing product offering we have made the determination to discontinue this product line in order to provide you with more advanced products while more efficiently managing our product portfolio.

Suggested replacements:

9006 Part Number	9001 Replacement
9006-05-00	9001-05-00
9006-05-01	9001-05-01
9006-12-00	9001-12-00
9006-12-01	9001-12-01
9006-24-00	9001-24-00
9006-24-01	9001-24-01

Coto Technology sincerely regrets any inconvenience caused by this product discontinuation. Please note that if you currently have open orders with the discontinued product, these orders must be canceled or converted to the recommended replacement listed above.

We appreciate your support and look forward to providing you with new and exciting products and designs by Coto, your technology leader in Providing Small Signal Switch and Sensing Solutions.

As always, should you have any questions please feel free to contact your Account Manager. For application support please e-mail <u>APPSupport@cotorelay.com</u>.

Best regards,

auce menter.

David Armenta 12/11/2020