Amphenol Canada Corp - Product Change Notice (PCN)

PCN Date	Feb.17,2022			
Supplier Name:	Amphenol Canada Corp.			
Amphenol Canada PCN Number	PCN-C1647			
Description of Change	Appearance and contact tail plating and some solder cup direction are different.			
Reason for Change	The mould of the original D-sub are aging and out of control lead time for D-subs parts.			
Summary of changes between new and old part	All of the contact tail are tin plating. The solder cup version middle row of contacts changed the solder cup opening direction. See the next page for the detail			
Traceability guidelines (lot code / date code, markings, ship date)	Data code - 2215			
Last Time Buy Date	N/A			
Datasheet attached? & Filename(s)	Refer to page 2 & 3			
Qual Test data attached? & Filename(s)	N/A			

Customer Part Number	Amphenol Old Part Number	Amphenol New Part Number	Effectivity	Samples Availability Date	Ruy Date	Expected Supplier Qual Date
NA	17EHD044PAA000 17EHD044SAA000	Unchanged	11-Apr-22	01-Apr-22	NA	NA
				For new sample		


Form # 9011065, Rev A

17EHD044PAA000

Old









- 1. The middle row of contact's solder cup is facing down.
- 2. Contact tails are gold flash plated.
- 3. Front shell tines appearance is minor difference with new version.

- 1. The middle row of contact's solder cup is facing up.
- 2. Contact tails are tin plated.
- 3. Front shell tines appearance is minor difference with old version.

