

Product Lifecycle Notice

Subject: Product Discontinuance / Obsolescence Notification Products

Publication Date: 4/12/2016

Revision Description: Initial release

initial release

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB (Life of Type Buy) / WITHDRAWN date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP / OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the lists and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

Regards,

ey Touvell

Jeffrey Touvell

Intersil Corporation

inter_{sil}"

| Exact Intersil Part # No other variation is being impacted. | Notice PLC16037 Issue Date | LTB / Withdrawn Date | Ship / Obsolete Date | Replacement / Similar / Re-Design |
|-------------------------------------------------------------|-------------------------------|-------------------------|-------------------------|-----------------------------------|
| 29104BJA | 4/12/2016 | 10/12/2016 | 4/12/2017 | 8403602JA or 8403603JA |
| EL4583CSZ-T7S2687 | 4/12/2016 | 10/12/2016 | 4/12/2017 | EL4583CSZ-T7 |
| EL5104ISZ | 4/12/2016 | 10/12/2016 | 4/12/2017 | EL5104IWZ-T7 |
| EL5104ISZ-T13 | 4/12/2016 | 10/12/2016 | 4/12/2017 | EL5104IWZ-T7 |
| EL5104ISZ-T7 | 4/12/2016 | 10/12/2016 | 4/12/2017 | EL5104IWZ-T7 |
| HA1-5330-5 | 4/12/2016 | 10/12/2016 | 4/12/2017 | None |
| HI3-0507-5Z | 4/12/2016 | 10/12/2016 | 4/12/2017 | HI3-0547-5Z |
| HI3-0516-5Z | 4/12/2016 | 10/12/2016 | 4/12/2017 | DG406DJZ/DG407DJZ |
| HI3-0546-5Z | 4/12/2016 | 10/12/2016 | 4/12/2017 | HI9P0546-9Z/HI4P0546-5Z |
| HI3-5051-5Z | 4/12/2016 | 10/12/2016 | 4/12/2017 | HI9P5051-9Z |
| HI4P0509-5Z | 4/12/2016 | 10/12/2016 | 4/12/2017 | DG409DYZ |
| HI4P0509-5Z96 | 4/12/2016 | 10/12/2016 | 4/12/2017 | DG409DYZ |
| HI4P0547-5Z | 4/12/2016 | 10/12/2016 | 4/12/2017 | HI3-0547-5Z |
| HI9P0509-5Z96 | 4/12/2016 | 10/12/2016 | 4/12/2017 | DG409DYZ |
| HSP50016JC-52 | 4/12/2016 | 10/12/2016 | 4/12/2017 | None |
| HSP50016JM-5296R3571 | 4/12/2016 | 10/12/2016 | 4/12/2017 | None |
| HSP50110JC-52 | 4/12/2016 | 10/12/2016 | 4/12/2017 | None |
| HSP50110JC-52Z | 4/12/2016 | 10/12/2016 | 4/12/2017 | None |
| HSP50110JI-52 | 4/12/2016 | 10/12/2016 | 4/12/2017 | None |
| HSP50110JI-52Z | 4/12/2016 | 10/12/2016 | 4/12/2017 | None |
| ISL22313TFU10Z | 4/12/2016 | 10/12/2016 | 4/12/2017 | ISL22313UFU10Z |
| ISL22313TFU10Z-TK | 4/12/2016 | 10/12/2016 | 4/12/2017 | ISL22313UFU10Z-TK |
| ISL78600ANZR5573 | 4/12/2016 | 10/12/2016 | 4/12/2017 | ISL78600ANZ |
| ISL78600ANZ-TR5573 | 4/12/2016 | 10/12/2016 | 4/12/2017 | ISL78600ANZ-T |
| ISL95901IRZ | 4/12/2016 | 10/12/2016 | 4/12/2017 | None |
| ISL95901IRZ-T | 4/12/2016 | 10/12/2016 | 4/12/2017 | None |
| TW8804-LC3-GRSHV | 4/12/2016 | 5/12/2016 | 5/12/2016 | TW8804-LC3-GRSH |
| TW8806EP-PB2-GRSHI | 4/12/2016 | 4/12/2016 | 4/12/2016 | TW8806EP-PB2-GRS |
| TW8806EP-PB2-GRSV | 4/12/2016 | 10/12/2016 | 4/12/2017 | TW8806EP-PB2-GRS |
| X28HC256JI-90R5697 | 4/12/2016 | 10/12/2016 | 4/12/2017 | None |
| X9C102SIZT2 | 4/12/2016 | 10/12/2016 | 4/12/2017 | X9C102SIZT1 |