1 Products affected

Product hierarchy no. 3	* Part no.	SBU	Type / Descri	Customer part no.			
SBU PG PUG Type							
02 006 016 00000015	516 See list below	Conntectors	CG Power Er	r n/a			
*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)							
List of part numbers affected							
3-126-516	CG10.6101.15	1 0016	.5101.151	CG20.6101.151	CG26.5101.151		
3-120-310	CG10.6101.15		.5101.151	CG20.0101.151	CG20.5101.151		
CG30.6101.151	CG30.6198.15	1 CG30	.6199.151	CG36.5101.151	CG40.6101.151		
CG46.5101.151	CG60.6101.15	1 CG66	.5101.151	CGA0.6101.151	CGC0.6101.151		
CGD6.5101.151	CGE0.6101.15	51 CGE0	.6133.151	CGF6.5101.151	CGG0.6101.151		
CGL0.6101.151							

2 Type of change

Modified packing and base quantity.

3 Detailed description of change



Product Change Notification				CG change of packing unit			
owner	creation date	release date	released by	change order no	rev	page	D10-048-691
sariogar	01.10.2020	15.10.2020	blumhe	2020728	А	1 of 2	

4 Reason of change

Card box and packaging unit changed from 5 pieces to 10 pcs for logistical reasons.

5 Release date

The change will be rolled-out starting ww 43/2020 (Date code 2043 or higher on label) and lasts approx. 6 months depending on the variant.

6 Impact of change and recommended action

Form	No	-
Fit	No	-
Function	No	-
Manufacturing	No	-
Label	Yes	Yes change on label
Packaging	Yes	Yes change in packaging

7 Reference Documents / Attachments

Kind of document	Remarks
CG Data Sheet	

Product Change Notification			CG change of packing unit				
owner	creation date	release date	released by	change order no	rev	page	D10-048-691
sariogar	01.10.2020	15.10.2020	blumhe	2020728	А	2 of 2	