

1 Products affected


Product hierarchy no. *	Part no.	SBU	Type / Description	Customer part no.			
SBU PG PUG Type				·			
02 007 003 0000002362	See list below	Connectors	1624	n/a			
*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)							

List of part numbers affected						
6163.0010	6163.0011	6163.0012	6163.0013	6163.0014		
6163.0023	6163.0024	6163.0026	6163.0027	6163.0028		
6163.0031	6163.0036					

2 Type of change

Change of approval markings on product and packaging label.

3 Detailed description of change



4 Reason of change

New Chinese CCC Approval certificate for the product type 1624.

5 Release date

The change will be rolled-out starting ww39/2019 (Date code 1939 or higher on label) and lasts approx. 6 months depending on the variant.

Product Change Notification				1624 change of marking				
owner	creation date	release date	released by	change order no	rev	page	D40 020 520	
sariogar	25.07.2019	23.09.2019	limachcl	2018079	Α	1 of 2	D10-038-530	



6 Impact of change and recommended action

Form Yes New CCC approvals marking added to molding body

Fit No Function No Manufacturing No -

Label Yes Approvals markings added to packaging label

Packaging No -

7 Reference Documents / Attachments

Kind of document	Remarks
Data sheet 1624	

Product Change Notification				1624 change of marking			
owner	creation date	release date	released by	change order no	rev	page	D40 030 E30
sariogar	25.07.2019	23.09.2019	limachcl	2018079	Α	2 of 2	D10-038-530