

## Sensirion Product Update for differential pressure series: SDP3x

SEN02-2018, Date: 2018-04-20

## 1. Description:

#### SDP3x-digital (SDP31, SDP32)

- Voltage range is extended (2.7 5.5V)
- Update frequency increased to 0.5ms
- Product number has been updated (post fix -01 to -02)
- o Product identifier that can be read out from the product has been updated

#### SDP3x-analog (SDP36, SDP37)

- Voltage range extended (2.7 5.5V)
- o TCS (Temperature compensation selection) pin is now available
- Operating temperature extended to -40 °C
- Product number has been updated (post fix -01 to -02)

#### **SDP33**

o Product number has been updated (post fix -01 to -02)

#### **Notes:**

- a. All current features of the SDP3x stay identical and making the **new SDP3x versions fully backward compatible.**
- b. Price table, packaging type, MOQ and lead times stay untouched

# 2. Latest Datasheets attached and in the Sensirion download center you will find:

https://www.sensirion.com/fileadmin/user\_upload/customers/sensirion/Dokumente/0\_Datasheets/ Differential Pressure/Sensirion Differential Pressure Sensors SDP3x Analog Datasheet.pdf

https://www.sensirion.com/fileadmin/user\_upload/customers/sensirion/Dokumente/0\_Datasheets/ Differential Pressure/Sensirion Differential Pressure Sensors SDP3x Digital Datasheet.pdf

https://www.sensirion.com/fileadmin/user\_upload/customers/sensirion/Dokumente/0\_Datasheets/ Differential Pressure/Sensirion Differential Pressure Sensors SDP33\_Datasheet.pdf

## Affected products incl. order code for SDP31, SDP32, SDP33, SDP36, SDP37

| New Part No.:       | Previous Part No.: | Product:               |
|---------------------|--------------------|------------------------|
| 1-101567- <b>02</b> | 1-101567-01        | SDP31-500Pa-TR-250pcs  |
| 1-101445- <b>02</b> | 1-101445-01        | SDP31-500Pa-TR-1.5kpcs |
| 1-101570- <b>02</b> | 1-101570-01        | SDP32-125Pa-TR-250pcs  |
| 1-101498- <b>02</b> | 1-101498-01        | SDP32-125Pa-TR-1.5kpcs |
| 1-101636- <b>02</b> | 1-101636-01        | SDP33-1500Pa-TR-250pcs |



| New Part No.:  | Previous Part No.:                | Product:   |
|----------------|-----------------------------------|------------|
| INCAN I GILINO | 1 1 C V 1 C G S 1 G 1 C 1 V C 1 . | i i Ouucti |

| 1-101571- <b>02</b> | 1-101571-01 | SDP36-500Pa-TR-250pcs  |
|---------------------|-------------|------------------------|
| 1-101471- <b>02</b> | 1-101471-01 | SDP36-500Pa-TR-1.5kpcs |
| 1-101572- <b>02</b> | 1-101572-01 | SDP37-125Pa-TR-250pcs  |
| 1-101497- <b>02</b> | 1-101497-01 | SDP37-125Pa-TR-1.5kpcs |



### 3. Timeline:

All above changes take place immediately.

## 4. Kindly requested actions on your side:

- a. Upload Datasheets
- **b.** All SDP31, SDP32, SDP36 and SDP37 stocks must be flushed from product numbers ending with -01. (-02 is the new product post fix).
- **c.** Please place orders with the new part no. Existing inventory should be sold after previous product has -01 part no.

For any question, please contact your regional Distribution Manager or <u>intl-sales@sensirion.com</u>

Best regards

Florian Hirsch

**Director Channel Sales** 

**Sensirion AG**