August 10, 2010

To: Our Valued Customers

Attention: Procurement Manager

Subject: PLC10081 – Product EOL/Obsolescence Notification

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB/WTHD date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP/OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the lists and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information. In the event that additional distribution outside of your internal organization is necessary, please notify Intersil and the distribution list for discontinued products will be updated as appropriate.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

Carl Sapp GCCN Customer Relations Dept. Intersil Corporation



	Exact Intersil Part #	Notice	LTD /	OLUD/	Replacement/
Date of	No other variation is	PLC10081	LTB / WTHD	SHIP/ OBSOLETE	Similar/
Change	being impacted.	Date	DATE	DATE	Re-Design
11-Aug-10	5962-9067802MXC	11-Aug-10	11-Feb-11	11-Aug-11	NONE
11-Aug-10	CD4504BDMSR	11-Aug-10	11-Feb-11	11-Aug-11	NONE
	5962R9666501VEC				
11-Aug-10	CD4504BHSR	11-Aug-10	11-Feb-11	11-Aug-11	NONE
	5962R9666501V9A				
11-Aug-10	CD4504BKMSR	11-Aug-10	11-Feb-11	11-Aug-11	NONE
	5962R9666501VXC				
11-Aug-10	CD4504BKMSRS9000	11-Aug-10	11-Feb-11	11-Aug-11	NONE
11-Aug-10	CD4504BKMSRS9002	11-Aug-10	11-Feb-11	11-Aug-11	NONE
11-Aug-10	HCTS138DMSR	11-Aug-10	11-Feb-11	11-Aug-11	NONE
	5962R9574001VEC				
11-Aug-10	HCTS138HMSR	11-Aug-10	11-Feb-11	11-Aug-11	NONE
	5962R9574001V9A				
11-Aug-10	HCTS138KMSR	11-Aug-10	11-Feb-11	11-Aug-11	NONE
	5962R9574001VXC				
11-Aug-10	HCTS138KMSRS9000	11-Aug-10	11-Feb-11	11-Aug-11	NONE
11-Aug-10	ISL1208IU8Z-TKR5288	11-Aug-10	11-Feb-11	11-Aug-11	ISL1208IU8Z-TK
11-Aug-10	ISL6592DNZ	11-Aug-10	11-Aug-10	11-Aug-10	NONE
11-Aug-10	ISL6592DNZ-T	11-Aug-10	11-Aug-10	11-Aug-10	NONE
11-Aug-10	ISL6592DNZ-TR5196	11-Aug-10	11-Aug-10	11-Aug-10	NONE
11-Aug-10	ISL6592DNZ-TR5197	11-Aug-10	11-Aug-10	11-Aug-10	NONE
11-Aug-10	JM38510/12302BEA	11-Aug-10	11-Feb-11	11-Aug-11	7705302EA
11-Aug-10	MG80C286-10/883	11-Aug-10	11-Feb-11	11-Aug-11	NONE

