ebmpapst

Product Change Notice

Date:	May 23, 2022	
Overview:	Part number 55462.40750 has been discontinued	
Reason for Change:	Low global demand	
Affected Part No(s):	55462.40750	
Design Change Detail:	Part number 55462.40750 has been discontinued due to low global demand	
Effective Date:	Immediately	
Last Time Buy Deadline:	N/A	
Pricing:	N/A	
ebm-papst employee:	Jeannine Zenobi	
Attachments:	N/A	
Comments:	There is no direct replacement available. Please contact us for a suggested alternative based on the application.	

Form No: 1274	Quality Record - No	Page 1 of 1
Rev. – Orig, Released 08/28/14	Retention Period – 1 year	Dept. Owner – Sales/Marketing

ebm-papst Inc. 100 Hyde Road · Farmington, CT 06034 · USA · Phone 860-674-1515 · Fax 860-674-8536 · sales@us.ebmpapst.com · www.ebmpapst.us