

Product Change Notification / SYST-13YAUY569

Date:

18-Apr-2022

Product Category:

Low-Med Voltage Power Modules

PCN Type:

Document Change

Notification Subject:

Data Sheet - MIC33153 - 4 MHz 1.2A Internal Inductor PWM Buck Regulator with HyperLight Load[®] and Power Good Revision

Affected CPNs:

SYST-13YAUY569_Affected_CPN_04182022.pdf SYST-13YAUY569_Affected_CPN_04182022.csv

Notification Text:

SYST-13YAUY569

Microchip has released a new Product Documents for the MIC33153 - 4 MHz 1.2A Internal Inductor PWM Buck Regulator with HyperLight Load[®] and Power Good of devices. If you are using one of these devices please read the document located at MIC33153 - 4 MHz 1.2A Internal Inductor PWM Buck Regulator with HyperLight Load[®] and Power Good.

Notification Status: Final

Description of Change:

1. Added new required note below the legend (for APID and some other former Micrel BUs) in Section 6.1 "Package Marking Information" to help clarify the marking codes.

2. Updated package type references and package outline images.

3. Minor formatting and text corrections throughout.

Impacts to Data Sheet: See above details.

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 18 April 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

MIC33153 - 4 MHz 1.2A Internal Inductor PWM Buck Regulator with HyperLight Load® and Power Good

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our PCN home page select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the PCN FAQ section.

If you wish to <u>change your PCN profile</u>, <u>including opt out</u>, please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections. Affected Catalog Part Numbers (CPN)

MIC33153-4YHJ-TR MIC33153YHJ-TR MIC33153-SYHJ-TR