

Littelfuse, Inc. 8755 West Higgins Road, Suite 500 Chicago, IL 60631 USA www.littelfuse.com

December 2, 2019

Product Discontinuation Notice for Select Temperature Sensor Products

Dear Valued Customers and Distributors:

Littelfuse would like to inform you of the discontinuation of select temperature sensor products due to low demand for more than two years.

- We can only accept a last time purchase order for these select products until February 3, 2020
- We will cease the manufacture of these select products from June 3, 2020

Please see Appendix A of this letter for the list of part numbers being discontinued.

Please contact your Littelfuse sales representative to make arrangement for a last time buy order for the affected part numbers. All last time buy orders will be **non-cancelable** and **non-returnable**.

Please respond to us by **January 10, 2020** to acknowledge receipt and understanding of this discontinuation notice. If we do not hear from you by the above mentioned date, we will expect that this discontinuation notice has been accepted and that no further action is required.

Best Regards,

Tim Patel Global Product Manager – Temperature Sensors Electronics Business Unit Littelfuse, Inc.



Expertise Applied | Answers Delivered

Product Discontinuation Notice for Select Temperature Sensor Products Appendix A – List of Discontinued Part Numbers

Page 1 of 1

Part Numbers			
BC103E6N	USP12431	USP19460	USP8786
BC363J2R-2	USP12646	USP19495	USP9565
KC104R6K	USP13862	USP19530-2	USW2972
KT503J6	USP15270	USP19624	USW3841
KW103G5	USP15776	USP19657	USW4249
LC102F2J	USP16095	USP19711	USW4310
LC104Q2J	USP17799-1	USP19729	USW4587
LC243J3G	USP18042	USP19750	USW4645
LR501D0J	USP18060	USP19766	USX1111
PT103J70	USP18144	USP1979	USX1247
PT222J17	USP18165	USP19855	USX2673
PX203G2	USP18256	USP20092	USX2925
SC103F3J	USP18578	USP3403	USX2970
USP10758	USP18763	USP3499	USX3477
USP11329	USP19228	USP4548	
USP11730-2	USP19378	USP5988	
USP12381	USP19406	USP7008	