

Product Change Notification

PCN-IFC-1160-2018

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
IFC - Industrial Field Connectivity	BF2	Product Change Notification	Notify Distributors and Field	8/21/2018

The following Phoenix Contact products have been modified. Existing specifications will be met or exceeded. Please review and acknowledge this document and inform your personnel as needed.

Description for Product Change Notification


For production reasons, an indentation was designed into the rear side of the contact carrier.
All electrical and mechanical data will remain unchanged.

Stock Status

Can existing stock still be used?	Yes
Is mixture of stock acceptable?	Yes

Transaction Dates

Date modification goes into effect from Germany:	1/1/2018
Expected first shipment (from Phoenix Contact) of the modified products(s):	1/1/2018





Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Change Notification

Should you have any issues with the timeline or content of this product change, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PCN within 30 days of delivery of the PCN; provided, however, that the failure to acknowledge receipt does not affect the product change or the effective date thereof.

Contact Info:

Samuel Hartman
shartman@phoenixcon.com

Thank you,

Nathan Owens

Product Marketing Manager - IFC



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300
Fax: 717-944-1625

Product Change Notification

Part #	Type Description
1521384	SACC-MINFS-5CON-PG 9
1521397	SACC-MINFS-5CON-PG13
1521517	SACC-MINFR-5CON-PG 9
1559071	SACC-MINFS-5CON-PG16
1521668	SACC-MINMS-5CON-PG 9
1521371	SACC-MINMS-5CON-PG13
1521504	SACC-MINMR-5CON-PG 9
1559039	SACC-MINMS-5CON-PG16