

PCN: PCN-CCX-43241-027-0

Product Change Notice

Change Type:

Issue Date: June 1, 2018

Add Laser Mark option to Product Marking

Parts Affected:

Product Family	MPN	Part Description
СС	BCM4401KQLG	10/100 ETHERNET PCI CONTR
СС	BCM5716SC0KPBG	DUAL PORT CONTR w/ INTEGRATED SerDes
СС	BCM5709CC0KPBG	Dual Port CNIC cntrlr w/intgrtd Cu PHY
СС	BCM5716C0KPBG	Dual Port CNIC cntrlr w/intgrtd Cu PHY
СС	BCM5715CKPBG	PCI-ExPREss DUAL PORT GbE CONTR(Pb-free)
СС	BCM57711EA0KPBG	Dual Port CNIC cntrlr w/intgrtd Cu PHY

Description and Extent of Change:

In order to improve reliability and prevent wear of the package's marking, Broadcom is gradually replacing ink marking with laser for all the above mentioned part-numbers.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The device FFF (Form, Fit and Function) specification will remain exactly the same. New marking will have no effect on IC reliability.

Effective Date of Change:

Product shipments will implement this change on or around August 2018. The expectation is a period of about six months will be required until all part numbers are modified per this PCN. Timing of the implementation will vary by part number depending on qualification completion, customer demand and inventory levels.

Please contact your Broadcom Inc. field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.