



# Product Change Notification

## TE Connectivity

Product Change Notification: E-18-019813

PCN Date: 18-DEC-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

MCP 1.5mm 5p MAIN plug HSG (1897234) // MCP 1.5mm 5p sub plug HSG (1897235)

**Description of Changes**

PLUG & CAP GAP REDUCTION - RIB ADDITION

**Other attachments:**

[MCP15 5P CONNECTOR IMPROVEMENT](#)

**Reason for Changes:**

Customer Request. CUSTOMER REQUEST

**Estimated Dates:**

**Last Order Date** (Obsolete Parts Only): **First Date To Ship** (Changed Parts Only):

19-APR-2019

**Last Ship Date** (Obsolete Parts Only): **Last Date for Mixed Shipments:** (Changed Parts Only):

22-NOV-2019

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1897208-1</a>	NO						

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1897208-1</a>	NO						

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1897208-1</a>	NO						