

Product Change Notification (PCN)

PCN Number

501823

Date Issued

November 09, 2016

Reason for Change

Obsolete

Change Type Description

This is to inform you that the part(s) referenced in this notice will be made obsolete due to low demand. Please contact your Molex Sales Engineer for additional questions concerning possible replacement part(s).

Planned Implementation Date

November 02, 2017

Recommended Replacement Parts

Please see the attached replacement parts list .xls file.

Last Time Buy Date for Obsolete Parts

September 04, 2017

Last Time Ship Date for Obsolete Parts

October 02, 2017

Before Change

 Molex is making housing 1625-6P with standard ears obsolete and replacing it with part 469990804 with pre-bent ears.





Straight ear option is obsolete

Replaced by pre-bent ear option

molex

After Change

Overview

- Molex is building a new mold to make 1625-6P housing in Lincoln. The new mold will make the standard ear option obsolete replacing it with a pre-bent ear option. The no ear options will also be made using the new mold.
 - The pre-bent ear option is a drop in replacement
 - There will be no impact to fit, form, function or appearance for no ear options
- Part Number Impact
 - 1625-6P housings
 - Assembly parts affected are listed on the attached impact report
- Qualification reports and samples from the new mold will be available after February 1, 2017
- Molex Confidential Information

 © 2016 Molex All Rights Reserved, Unauthorized Reproduction/Distribution is Prohibited.





Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:501823" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com Molex Part # 3062061

Replacement parts list

Molex Part	Replacement part	
Number	number:	Replacement type
3062062	469990804	Drop in replacement

Replacement part has pre-bent panel mount ears.	Option text if differences is choose
	Replacement part has pre-bent panel mount ears.