

Global Change Notification (GCN)

Product Family	Gigajack Single Ports	10683562
		GCN Number
Series	85759, 85789, 85791, 85793	April 29, 2015
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	This notice is to inform on the replacement of the RJ-45 contact & overmold tooling. This change is urgently required to replace existing tooling and ensure component supply. The RJ-45 component from the new tool will be identical to the existing component, no change in form or materials. All product produced from the implementation date will use the new tooling.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Force Majeure	
Assessment Of Change (How Product Will Be Qualified & Validated)	The new parts will undergo a full first part inspection.	
Internal Molex Qualification Date (Planned Date Information Available)	May 08, 2015	
Sample Availability Date (Changed Part)	May 15, 2015	
Date of Implementation	June 01, 2015	
Method of Identifying Change	There will be no difference in form, fit or function of the new product.	
Recommended Replacement Parts		
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com

Material

857891003

857911020

857914020

857591001

857891001

857891006

857931001

857931003

857931006

857931013

857931020

857931007

857931012

857595001

857894008

857894020