

	PRODUCT	CHANG	E NOTIF	FICATIO	N
Product Category	COPPER - CABLE - 1G				20220105-1
Product Group	BULK COPPER CABLE				
ISSUE DATE:				•	
IMPACTED REGIONS:	✓ NA	✓ EMEA	✓ LATAM	✓ AP	•
REASON FOR CHANGE:	✓ DISCONTINUATION				
	OTHER				
DESCRIPTION OF CHANGE: (Required)				
performance with headroom	n equivalent or better th		_	sized pathway.	The new SC+ cable has the same
Photos/Drawing (where applications)		T PART NUMBEI	RS: (where appli	icable)	
Reference Page 2 / Linked	I PDF				

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

	Year	Month	Day
SCHEDULE FOR CHANGE	(YYYY)	(MM)	(DD)
New product sample availability date	2022	1	5
Old product discontinuation date*	2022	4	5

^{*}Important: A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s) Compatibility Type Replacement Part 1

PUP6AS04BU-G Direct
PUP6AS04WH-G Direct
PUP6AS04BL-G Direct
PUP6AS04GR-G Direct
PUP6AS04IG-G Direct
PUP6AS04OR-G Direct
PUP6AS04OR-G Direct
PUP6AS04RD-G Direct
PUP6AS04VL-G Direct
PUP6AS04YL-G Direct
PUP6AS04YL-G Direct
PUP6ASD4YL-G DIRECT
PUP6ASD4YL-G PUP6ASD04YL-G