

**Products Affected:** 

ASSMANN WSW components, Inc. 1840 W. Drake Drive, Suite 101 Tempe, AZ 85283 Toll Free 877.277.6266 www.assmann.us

## **Product Change Notification (PCN)**

Issue Date:11/15/2016Modification/Revision Date:6/18/2018

## DIP

Change Notification:	PCN-US-20161102-DIP
Description of changes:	End of component Life
Date of change and Implementation:	Change: 11/15/2016
Key Characteristics of Change:	End of component Life

Reason for Change:	Part number unification
Response:	No response to this notification is required.
Revision 1:	Amended PCN by adding ADIP18-G-LC to the list of EOL parts.

**ADIPXX-G-LC** 



ASSMANN WSW components, Inc. 1840 W. Drake Drive, Suite 101 Tempe, AZ 85283 Toll Free 877.277.6266 www.assmann.us

## Product Change Notification (PCN)

Issue Date:11/15/2016Modification/Revision Date:6/18/2018

## **Reference Documents / Attachments:**

**Document: Drawing** 

Previous part number	New part number
ADIP08-G-LC	No replacement
ADIP10-G-LC	No replacement
ADIP14-G-LC	No replacement
ADIP16-G-LC	No replacement
ADIP18-G-LC	No replacement
ADIP20-G-LC	No replacement
ADIP24-G-LC	No replacement
ADIP28-G-LC	No replacement
ADIP40-G-LC	No replacement