

Product Change Notification

TE Connectivity

Product Change Notification: P-20-018970

PCN Date: 24-APR-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

SR4M/D & SR6 relay series

Description of Changes

Correction of the product environmental compliance coding in the corresponding statement of compliance (SoC) regarding REACH SVHC BPA and establishment of a relationship to a BPA RSCD on TE.com.

Other attachments: example SoC

RSCD BPA

Reason for Changes:

Document clarification.Dear customer! In our SR4M/D & SR6 relay series, since September 2017 we use an adhesive, which contains SVHC BPA above REACH threshold of 0.1%. Our Statement of Compliance for the relays did not consider this fact, as it is based on a material declaration from our supplier, which turned out to be wrong. After detecting this error, since March 2020 we corrected the product compliance declaration accordingly and these are linked to the affected products on our homepages. We are working to find potential alternative adhesives, which might enable us to declare containing REACH SVHC below threshold again, but for the time being, the SoC similar to the enclosed is valid for the SR4M/D & SR6 relay series. Apologies for any inconveniences caused.

Estimated Dates:	
------------------	--

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	24-APR-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1202260 4	NO			"V23050-A1012-A542",			
<u>1393260-4</u>	NO			"V23050A1012A542"			
<u>1415015-1</u>	NO			"V23050-A1024-A533", "V23050A1024A533"			
<u>1415055-1</u>	NO			"SR4D4012"			
<u>3-1415018-1</u>	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415054-1	NO			"SR4M4048"			
3-1415353-1	NO			"SR6M4024"			
4-1415053-1	NO			"SR4M4024"			
5-1415019-1	NO			"V23050-A1110-A551", "V23050A1110A551"			
5-1415053-1	NO			"SR4M4005"			
5-1415539-2	NO			"SR6V6K24"			
6-1415027-1	NO			"SR6D4024"			
6-1415053-1	NO			"SR4M4006"			
6-1415054-1	NO			"SR4M4110"			
6-1415055-1	NO			"SR4D4048"			
6-1415537-5	NO			"SR6A6K24"			
7-1415054-1	NO			"SR4D4005"			
8-1415053-1	NO			"SR4M4012"			
8-1415537-0	NO			"SR6B6K24"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>1393260-4</u>	NO			"V23050-A1012-A542", "V23050A1012A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
1415055-1	NO			"SR4D4012"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415054-1	NO			"SR4M4048"			
3-1415353-1	NO			"SR6M4024"			
4-1415053-1	NO			"SR4M4024"			
5-1415019-1	NO			"V23050-A1110-A551", "V23050A1110A551"			
5-1415053-1	NO			"SR4M4005"			
6-1415027-1	NO			"SR6D4024"			
6-1415053-1	NO			"SR4M4006"			
6-1415054-1	NO			"SR4M4110"			
6-1415055-1	NO			"SR4D4048"			
6-1415537-5	NO			"SR6A6K24"			
7-1415054-1	NO			"SR4D4005"			
8-1415053-1	NO			"SR4M4012"			
8-1415537-0	NO			"SR6B6K24"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			

Part Number(s) being Modified:

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part Number(s)		Substitute Alias Part Number(s)	Description Of Difference
Number	per PCN	Drawing	Number	,	Number		
1393260-4	NO			"V23050-A1012-A542",			
1393200-4	NO			"V23050A1012A542"			
1415015 1	NO			"V23050-A1024-A533",			
<u>1415015-1</u>	NO			"V23050A1024A533"			
1415055-1	NO			"SR4D4012"			
2 1 1 1 5 0 1 0 1	NO			"V23050-A1021-A533",			
3-1415018-1	NO			"V23050A1021A533"			
3-1415054-1	NO			"SR4M4048"			
3-1415353-1	NO			"SR6M4024"			
4-1415053-1	NO			"SR4M4024"			
				"V23050-A1110-A551",			
<u>5-1415019-1</u>	NO			"V23050A1110A551"			
5-1415053-1	NO			"SR4M4005"			
6-1415027-1	NO			"SR6D4024"			
6-1415053-1	NO			"SR4M4006"			
6-1415054-1	NO			"SR4M4110"			
6-1415055-1	NO			"SR4D4048"			
6-1415537-5	NO			"SR6A6K24"			
7-1415054-1	NO			"SR4D4005"			
8-1415053-1	NO			"SR4M4012"			
8-1415537-0	NO			"SR6B6K24"			
0 1 1 1 5 0 1 0 1	NO			"V23050-A1110-A533",			
9-1415018-1	NO			"V23050A1110A533"			

Part	Part Discontinued	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	per PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>5-1415539-2</u>	NO			"SR6V6K24"			