

## **Global Change Notification (GCN)**

**Product Family** DIN 10708005 GCN Number Series 121023,121024,121064,121065,121178,121205,121206,1212 August 17, 2015 Date Issued Reason For Change Upgrade / Rearrangement Of Tooling / Equipment This is to inform you that Molex is adding a radius to the moulded housing for its DIN Change Description form-Micro inserts. The larger radius will remove stress concentration and make the parts much stronger and robust hence improving the quality of our connectors. Radius added Radius added Before After Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message. Reason For Short Notice Exception 8D Corrective Action Changes Assessment Of Change This change has no affect on fit or function of the parts. Report available upon request. (How Product Will Be Qualified & Validated) Internal Molex Qualification Date August 12, 2015 (Planned Date Information Available) Sample Availability Date July 13, 2015 (Changed Part) Date of Implementation August 24, 2015 Method of Identifying Change The customer will see no change to this part as the changes are internal Recommended Replacement Parts N/A Last Time Buy Date for Obsolete Parts Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com