

Product Group: CC/Mon Nov 15, 2021/PTN-CC-00006-2021-REV-0

## **Obsolescence of Certain Power Capacitors**

**DESCRIPTION OF CHANGE:** Due to shrinking market demand it is not feasible anymore to support the ceramic power capacitors mentioned.

**REASON FOR CHANGE:** Due to shrinking market demand it is not feasible to keep the special manufacturing and testing equipment for the ceramic power capacitors mentioned herein running.

EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE: N/A

PART NUMBERS/SERIES/FAMILIES AFFECTED: Please see materials list on the succeeding page.

VISHAY BRAND(s): Vishay Draloric

TIME SCHEDULE:

Last Time Buy Date: Thu Sep 1, 2022 Last Time Ship Date: Wed Mar 1, 2023

**SAMPLE AVAILABILITY: N/A** 

PRODUCT IDENTIFICATION: by part number

**QUALIFICATION DATA: N/A** 

This PCN is considered approved, without further notification, unless we receive specific customer concerns before Fri Apr 1, 2022 or as specified by contract.

ISSUED BY: Dr. Florian Weyland, Florian.Weyland@vishay.com

For further information, please contact your regional Vishay office.

## **CONTACT INFORMATION:**

Americas	Europe	Asia	
Martin Leupold	Martin Leupold	Boonhooi Tan	
DrFelix-Zandman-Platz 1	DrFelix-Zandman-Platz 1	37A Tampines St. 92 #07-00	
Selb Germany 95100	Selb Germany 95100	Singapore Singapore 528886	
Phone: +49-9287-71-2535	Phone: +49-9287-71-2535	Phone: +65-6780-7759	
Fax: +49-9287-71-2675	Fax: +49-9287-71-2675	Fax: +65-6780-7749	



## **Product Termination Notification**

Product Group: CC/Mon Nov 15, 2021/PTN-CC-00006-2021-REV-0

TDZ50124WN25136CB1	TDZ50124WN25136CB2	TDZ50124WN20136CB1	TDZ45124WN10133CB1	TDZ45124WN10136CB1
TDZ45124WW10133CB1	TDZ45124WW10136CB1	TDZ45124WN15136CB1	TDZ45124WY15136CB1	TDZ50098WN25136CB1
TDZ50141WN30136CB2	TDZ50157WN35136CB2	TDZ50124WN20133CB2	TDZ50124WN20136CB2	TF125213WN50136CB1
TF125260BE10236CB1	TF125260BE20236CB1	PZ0140WL24190CB1	FPZ140WV50036CB1	FPZ140WV50038CB1
FPZ140WV75036CB1	PZ0140WL10136CB1	PZ0140WL10136CB2	PZ0140WL10138CB1	PZ0140WL50038CB1
DBZ55135WP10136CB1	DB055135WP10136CB1	DB055135WP10138CB1	BZ100110WV50036CB1	BZ100110WV50033CB1
BZ100110BJ68036CB1	BZ120055WC25136CB1	BW118115WV125P36CB	BW118115XT125P36CB	BZ080110WV25036CB1
BZ080110WV25036CB2	BZ118100WV10136CB1	BZ118078WV50036CB1	BZ118078WV75036CB1	BZ120055WC16136CB1
DBF50166BQ125P36CB	DBF50166BQ12536CB1	DBF50166BQ12536CB1	TDZ50172WN40136CB2	