



---

# ESSENTRA

COMPONENTS

09 September 2020

To whom it may concern:

This is to inform you that Essentra has obsoleted part number R1209-093. Unfortunately, our tool for this part has been damaged beyond repair. Sales do not justify us making a new tool. The closest equivalent part is R1209-093. This is effective immediately. I apologize for any inconvenience.

Please let me know if you have any questions.

Best Regards,

Greg P. Mifsud  
Director of Product Management

---

**ESSENTRA COMPONENTS**

3123 Station Road  
Erie, PA 16510  
United States of America

T (800) 899-9440  
F (814) 899-2586  
E [saleserie@essentracomponents.com](mailto:saleserie@essentracomponents.com)  
[www.essentracomponents.com](http://www.essentracomponents.com)