Product/Process Change Notifications



PCN - 21 009

2021

Amphenol Information Communication and Commercial Products Group www.amphenol-icc.com

Release Date:	February	08
Release Date.	rebluary	00

Subject: Notification of Planned Change Distribution: Affected Customers Type of Change: End of Life Change Description: End of life of listed products With market application change: a few of tooled products had been replaced by pext generation version		1		· · · · · · · · · · · · · · · · · · ·	
Power Receptacle Product Manager: Chris Liu Subject: Notification of Planned Change Distribution: Affected Customers Type of Change: End of Life Change Description: End of life of listed products Reason for Change: With market application change, a few of tooled products had been replaced by next generation version to meet market needs, these parts are planned to be end of life. Affected Parts: 10009536-01-LF; 10025058-2112LF; 10025058-2122LF; 10025058-2111LF; 10025058-2122LF; 10025058-2112LF; 10025058-2122LF; 10025058-2112LF; 10025058-2112LF; 10025058-2122LF; 10025058-2112LF; 10025058-2112LF; 10025058-2122LF; 10025058-2112LF; 10025058-212LF; 10025058-2112LF; 10025058-212LF; 10025058-21	Product Name	AIRMAX VS			
Subject: Notification of Planned Change Distribution: Affected Customers Type of Change: End of Life Change Description: End of life of listed products Reason for Change: With market application change, a few of tooled products had been replaced by next generation version to meet market needs, these parts are planned to be end of life. Affected Parts: 10009536-011E;10025058-2112EF;10025058-2112EF;10025058-2111EF; 10025058-2111EF; 10025058-2112EF;10025058-2112EF;10025058-2112EF;10025058-2111EF; 10025058-211EF; 10025058-21EF Satistier Disty Return Date: Satistier Date: Sat		Power Receptacle			
Distribution: Affected Customers Distribution: Affected Customers Type of Change: End of Life Change Description: End of life of listed products Reason for Change: With market application change, a few of tooled products had been replaced by next generation version to meet market needs, these parts are planned to be end of life. Affected Parts: 10009536-01LF;10025058-2112LF;10025058-2122LF;10025058-2112LF;10025058-2122LF;10025058-2112LF;10025058-2122LF Effective Date of Change: July 15, 2021 Last Time Buy Date: May 10, 2021 Earliest Disty Return Date: August 10, 2021 Datasheet Attached? Qual/Test Data Attached? Contact your local AICC Representative, or Product Manager Questions? Contact your local AICC Representative, or Product Manager Contact your local AICC Representative, or Product Manager	Product Manager:	Chris Liu			
Type of Change: End of Life Find of Life Change Description: End of life of listed products Reason for Change: With market application change, a few of tooled products had been replaced by next generation version to meet market needs, these parts are planned to be end of life. Affected Parts: 10009536-001LF;10025058-2122LF;10025058-2122LF;10025058-2111LF ; 10025058-2122LF;10025058-2122LF;10025058-2122LF;10025058-2122LF;10025058-2122LF;10025058-2122LF;10025058-2112LF ; 10025058-2112LF ; 10025058-2122LF;10025058-2112LF ; 10025058-2112LF ; 10025058-2112LF ; 10025058-2112LF ; 10025058-2112LF ; 10025058-2112LF ; 10025058-2112LF ; 10025058-2122LF;10025058-2112LF ; 10025058-2112LF ; 10025058-212LF ; 10025058-212LF ; 10025058-2112LF ; 10025058-2122LF ; 10025058-212LF ; 10025058-2122LF ; 10025058-2122LF ; 10025058-212LF ; 10025058-2122LF ; 1002	Subject:	Notification of Planned Change			
Change Description: End of life of listed products Reason for Change: With market application change, a few of tooled products had been replaced by next generation version to meet market needs, these parts are planned to be end of life. Affected Parts: 10009536-001LF;10025058-2112LF;10025058-2122LF;10025058-2111LF ; 10025058-2112LF;10025058-2122LF;10025058-2111LF ; 10025058-2112LF ; 10025058-212LF ; 10025058-2112LF ; 10025058-2112LF ; 10025	Distribution:	Affected Customers			
Reason for Change: With market application change, a few of tooled products had been replaced by next generation version to meet market needs, these parts are planned to be end of life. Affected Parts: 10009536-001LF;10025058-2112LF;10025058-2122LF;10025058-2111LF ; 10025058-1122LF;10025058-2122LF;10025058-2112LF ; 10025058-2111LF ; 10025058-1122LF ; 10025058-2112LF ; 10025058-210E ; 10025050 Image: Image: Image: Imag	Type of Change:	End of Life			
Reason for Change: to meet market needs, these parts are planned to be end of life. Affected Parts: 10009536-001LF;10025058-2112LF;10025058-2122LF;10025058-2111LF; 10025058- Effective Date of Change: July 15, 2021 Last Time Buy Date: May 10, 2021 Earliest Disty Return Date: August 10, 2021 Datasheet Attached? Image: State Sta	Change Description:	End of life of listed products			
Affected Parts: 1122LF;10025058-1222LF Effective Date of Change: July 15, 2021 Last Time Buy Date: May 10, 2021 Earliest Disty Return Date:	Reason for Change:				
Last Time Buy Date: May 10, 2021 Earliest Disty Return Date: August 10, 2021 Last Time Shipment Date August 10, 2021 Datasheet Attached? August 10, 2021 Qual/Test Data Attached? Alcorect Manager Available Alternatives? Contact your local AICC Representative, or Product Manager Chris Liu	Affected Parts:				
Earliest Disty Return Date: August 10, 2021 Last Time Shipment Date August 10, 2021 Datasheet Attached? Image: Contact your Image: Contact you	Effective Date of Change:	July 15, 2021			
Last Time Shipment Date August 10, 2021 Datasheet Attached?	Last Time Buy Date:	May 10, 2021			
Datasheet Attached?	Earliest Disty Return Date:				
Qual/Test Data Attached? Image: Contact your local AICC Representative, or Product Manager Questions? Image: Chris Liu	Last Time Shipment Date	August 10, 2021			
Samples Availability Date:	Datasheet Attached?				
Available Alternatives? Image: Contact your local AICC Representative, or Product Manager Questions? Chris Liu	Qual/Test Data Attached?				
Questions? Contact your local AICC Representative, or Product Manager	Samples Availability Date:				
Questions?	Available Alternatives?				
	Questions?	Contact your local AICC Representative, or Product Manager			
8866 9210/ Chris.Liu@fci.com		Chris Liu			
		8866 9210/ Chris.Liu@fci.com			

Note:

Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection.