https://ams-osram.com

Sensing is life

CIMUN OSRAM

01 March 2023

Not For New Design OS-NFND-2023-003

 Expected discontinuation date:
 < 1 year</td>

 Reason:
 The following products have reached their end of life.

 OSRAM OS Expectations:
 Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions. Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products. Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.



Please direct your feedback to your local Sales office.

Expected discontinuation date:

< 1 year

Reason:

The following products have reached their end of life.

Not for new design products				Recommended Replacement		
Device	Ordering Code	Brand	Expected PDN start	Device	Datasheet Ordering Code	Brand
GW JTLMS2.EM-G7H3-XX510-1-60-R33	Q65113A1407	DURIS	01.06.2023	n/a	No replacement	
GW JTLMS2.EM-G9H5-XX58-1-60-R33	Q65113A1408	DURIS	01.06.2023	n/a	No replacement	
GW JTLMS2.EM-GVH6-XX57-1-60-R33	Q65113A1409	DURIS	01.06.2023	n/a	No replacement	
GW JTLMS2.EM-GVH6-XX56-1-60-R33	Q65113A1410	DURIS	01.06.2023	n/a	No replacement	
GW JTLMS2.EM-GWH7-XX55-1-60-R33	Q65113A1411	DURIS	01.06.2023	n/a	No replacement	
GW JTLMS2.EM-GWH7-XX53-1-60-R33	Q65113A1412	DURIS	01.06.2023	n/a	No replacement	
GW JTLMS2.EM-GWH7-XX52-1-60-R33	Q65113A1413	DURIS	01.06.2023	n/a	No replacement	
GW JTLMS2.EM-GWH7-XX51-1-60-R33	Q65113A1414	DURIS	01.06.2023	n/a	No replacement	